Technical Service Bulletin 27 Battery discharged on vehicles with Advanced Key

Condition

REVICION	HISTORY	WH St.		
Revision	Date	Purpose		
4	-	Revised header data (Added model years)		
3	8/7/2009	Revised header data		
2	2/27/2009	Revised Condition (Software) Revised Service (SVM table)		
1	11/5/2008	Original publication		

Transaction No.: 2019143

- The customer may report that the engine doesn't start due to a discharged vehicle battery.
- Possibly affected vehicles must have to following equipment:
 - Audi Advanced Key (PR No. 472, 4K7 or 4l3).
 - Control unit for access and start authorization J518 (address 05) SW version below 240 (4F0 905 852 E) or below 50 (4F0 905 852 C).

Technical Background

nonger possible.

New software in the control unit for access and start authorization (J518) resolved the problem.

Service Pressing the start button while the ignition key is not in the vehicle wakes the CAN comfort

Connect the vehicle to an approved charger or voltage maintainer and verify the battery state of health with the "Battery Test Plan" in the 61 - energy management control unit J644.

Recharge or replace the battery according to the result.

ip: When replacing the battery, all necessary documentation must be attached to the work order.

- Use the history data from the energy management control unit J644 (address 61) to verify whether an awake CANbus or customer influence (e.g. ication or ext. lights on) has discharged the vehicle battery.
- If an awake CANbus is confirmed, try to reproduce the condition.
 - Disconnect the battery charger/maintainer, if applicable.
 - Switch off ignition.
 - Remove all keys from the vehicle. c.
 - Press the start button and measure the closed-circuit current of the vehicle battery.
- If the condition can be reproduced, perform a SVM software update of the control unit for access and start authorization J518 (address 05).

SVM Update Instructions

- Follow the instruction in the attached TSB 2011732 00 Software Version a.

 Management (SVM), operating instructions.
- b. Update the control unit for access and start authorization J518 (address 05) using SVM action code as listed in the table below if necessary.

Control unit for access and start authorization 3518	Old Software Version	New Software Version	SVM Action Code
"POF		(or higher)	PDFC
4°F0 905 852 B	< 240	240	For A6:

cox			or com
eato			4F05A004
4F0 905 3.52 C	< 50	50	For Audi Q7:
"bo,			4L05A00:

Warranty

la.	Service Bulletin is informational only.	<u> </u>			
Service Number:	9666				
Damage	0039				
Code:		C			
Labor Operations:	Battery charging preparation	2706 8350	10 TU		
	Replace battery, if necessary	2706 55 50	50 TU (Q7)		
	according to battery test plan	2706 55 00	70 TU (A6)		
Diagnostic	GFF MIN.S.	0150 0000	Time stated on		
Time:	191		diagnostic protocol		
	Road test their to service procedure	No allowance	0 TU		
	Road test after service procedure	No	0 TU		
	<u>on</u>	allowance			
	Technical dia mosis at dealer's discretion				
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details) As per TSB #2019143/4				
Claim	As per TSB #2019143/4		artPV		
Comment			SM		
Ilana,		ntip://			
, ,		.kQ://			

Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and Service refera

http://www.smartp.DF.Creator.com

Always check with your Parts Department and service manuals for the latest information.

©2009 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these or ext. materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

http://www.smarthplic.com