Technical Service Bulletin

Transactio. No.: 2010034/8

37 Ignition key cannot be removed when transmission is in park or cannot lock vehicle

itor.com

Release date: Aug 19, MNSM 2009

Condition

ISION HISTORY

Revision	Date	Purpose
8	-	Revised header data (New customer codes)
7	11/25/08	Revised Title to include Repair Group

The ignition key cannot be removed from the switch, despite selecting shift position P.

- Or, if equipped with advanced key system, the vehicle cannot be locked by remote control after exiting.
- DTC 00230 (Switch for gearbox position P-P305, disruption/short circuit to positive/ground, sporadic) may be logged in the 05-vehicle authorization system.

Technical Background

The selector lever adjustment is sporadically is not recognized. Therefore, the ignition key cannot be removed from the switch or the locking of the vehicle is prevented.

Production Solution

- Modified selector mechanism from VIN 4F_5N037400.
- In MY 06, unit selector mechanism introduced from VIN 4F_6N116844.
- DFCreator.com Switch for gearbox position P (F305) changed from week 16/08, VIN: 4F_8N138012.

Service

1. Check for other DTCs that may be logged in other control units, such as ABS, vehicle authorization system, engine, gearbox, etc. Address any DTCs according to Guided ut. Maran Ingeligit http://www

Fault Finding.

eator.com Note: Lubicants and oils can contaminate the micro switches (F305) and lead to long-term da nage. Do not apply lubricants such as silicon oil to the gearshift housing, even if the gearshift housing appears to be stiff.

2. If this complaint occurs on vehicles with Multitronic transmission (CV) in combination with (gearbox) DTCP0706 (Transm. Range Sensor Circ. Range/ erformance), then:

If the vehicle is model year 2006, replace the Transmission Control Module.

- If the vehicle is model year 2007 or newer, open a TAC report with an attachment of the DTCs. Reference this Technical Service Bulletin and contact the Technical Assistance Center.
- 3. If no other DTCs are logged, or all other DTCs are addressed, proceed as follows:

Case A - Vehicles produced before VIN 4F 5N037400

itor.com

Replace the complete selector mechanism.

Case B - Vehicles produced between VIN 4F 5N037400 and VIN 4F 8N138012

- Read the DTC memory. If DTC is logged in Access/Start Control System group 1. 05. follow Guided Fault Finding
- Carry out the checks described in the attachment (Checklist for A6 Transmission 2. Selector Mechanism). Record every step in the checklist.

Tip: With all complaints in connection with the A6 selector mechanism after VIN 4F_5N037400, the attached checklist must be completed.

Repair if necessary. 3.

If no problem is found, replace the wiring loom with micro switch 4F0-971-697. 4.

tor.com

Attach the completed checklist and VAS printouts to the repair order. Warranty-5. requested documents received without checklist and VAS printouts will be denied http://www.smartpf payment.

Case C Vehicles produced after VIN 4F 8N138012 http://www.

		of com			orcom			
Open a TAC contact. Attach the GFF log. Make reference to this TSB number in the TAC contact and call the Technical Assistance Center for assistance.								
	Warranty							
	Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.						
	Service	3710						
Lice	Number:	V ¹⁰⁷						
	Damage Code:	0011						
	Labor	Remove and install shift	37 15 19 XX	Use repair operation for				
	Operations:	mechanism		specific vehicle				
		Complete checklist	37 10 99 93	50 TU max				
		Dismantle selector	37 03 37 50	70 TU				
		mechanism	8					
		Remove and reinstall	3730 19 00	250 TU				
		multitronic (CVT) TGM						
		2006 model year only						
	Diagnostic	GFF	01 50 00 00	Time stated on diagnostic				
	Time:			protocol				
		Road test prior to service	No allowance	0 ТU				
		procedure			com			
		Road test after service	No	0 ТU	, or .			
		procedure	allowance					
	Ś	Pechnical diagnosis at dealer's						
	anal	(Refer to Section 2.2.1.2 and A						
	N.S.	details)						
	1202	llan						
ntte	*		n ^{iti}	8.				

Claim

As per TSB #2010094/8

con

Comment:

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

FCreator.com

Recuired Parts and Tools

Required Parts and To Use ETKA to find VIN-s	ols specific parts references.	o: Ilwww	<u></u>
Part Number	Part Description	11 feet	Quantity
4F0-971-697	Wiring loom with micro switch		1

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2009 Audi of America, Inc.All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make manges at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publishe

http://www.smartpDFCreator.com http://www.smartp.brcreator.com