



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355
dsw@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2010 AUDI A4

Mfg Bulletin #: TSB-37-12-35 Repl Bulletin #: Bulletin Date: 20120126

Component: 013000 STEERING:GEAR BOX (OTHER THAN RACK AND PINION)

AUDI: WARNING LIGHT FOR GEARBOX COMES ON. *PE

TSB Report for: 2010 AUDI A4

Mfg Bulletin #: TSB-37-13-09 Repl Bulletin #: Bulletin Date: 20130719

Component: 013000 STEERING:GEAR BOX (OTHER THAN RACK AND PINION)

AUDI: IN SOME VEHICLES, THE CLUTCHES, AFTER HAVING TORQUE CONVERTER, COMPLETE GEARBOX REPLACEMENT OR MECHATRONICS, MUST ADAPT TO NEW COMPONENTS WITH GRADUAL MOVING OF CLUTCH LININGS IN MOST DIVERSE LOAD CONDITIONS. MODELS 2004-14, A3, TT,

TSB Report for: 2010 AUDI A4

Mfg Bulletin #: TSB-48-10-07 Repl Bulletin #: Bulletin Date: 20100527

Component: 011000 STEERING:WHEEL AND HANDLE BAR

AUDI: SERVOTRONIC STEERING (1N3) SHUDDER AT LOW SPEED WHILE TURNING. WHILE DRIVING AT LOW SPEEDS (BELOW 5MPH), A SHUDDER OR KNOCKING NOISE WOULD OCCUR IN STEERING WHEEL WHEN TURNED DURING PARKING LOT MANEUVERS. *PE

TSB Report for: 2010 AUDI A4

Mfg Bulletin #: TSB-48-13-56 Repl Bulletin #: Bulletin Date: 20131213

Component: 010000 STEERING

AUDI: WHEN VEHICLE IS STATIONARY, THE STEERING WILL FEEL STILL WHEN TURNING AND THE STEERING SHAFT NEEDS TO BE UPDATED WITH IMPROVED INTERMEDIATE STEERING SHAFT. MODEL 2009-2014 A4, A5, A5 CAB, Q5. *PE

TSB Report for: 2010 AUDI A4

Mfg Bulletin #: TSB-48-14-61 Repl Bulletin #: Bulletin Date: 20140710

Component: 010000 STEERING

AUDI: WHEN TURNING, THE STEERING FEELS STIFF AND OCCURS EVEN WHEN VEHICLE IS STATIONARY. INTERMEDIATE STEERING SHAFT NEEDS TO BE IMPROVED. MODEL 2008-2014 A4, A5, Q5. *PE

***** END OF REPORT *****