tor.com Transaction No.: 2014 231/4

Release dote: May 4, 2009

MM.SIT

Technical Service Bulletin 91 Cursor is jumping in radio memory list (possible Navigation DVD upgrade)

Condition

VISION HISTORY

ζ.		-88		
	Revision	Date	Purpose	
	4	-	Revised Service (Added latest MMI Zug update)	
	3	11/11/2008	Revised Title to include Repair Croup	

When trying to select another stored station in the Radio Menory station list, the cursor is not following the selection. Instead the cursor is jumping to the top of the displayed list and the desired station can't be selected. In other cases the cursor can't be scrolled to the next or .se previous page.

Technical Background

MMI system software issue.

Production Solution

Improved software.

Service

An MMI system Software update is required. Refer to Technical Service Bulletin 2019334 for directions to perform the update.

,DFCreator.com Tip: Due to the incompatibility of Navigation DVD Version 4 and lower with the new MMI software, it may be necessary to replace the installed DVD with a Navigation DVD Version 5. Refer to Technical Service Bulletin 2019334 for more information.

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is
. Ilman	-Ilmon
n ^{ttp.}	nttp

		r.com	x cor	9.		
		informational only.	eato			
	Service	G196	OFC1			
	Number:					
	Damag-Code:	0039				
	Labor	MMI Zug update without installed telephone transceiver R36	9196 25 99	100 TU		
with	Operations:	MMI Zug update with installed telephone transceiver R36	9196 26 99	150 TU		
	Diagnostic	GFF	No allowance	0 TU		
	Time:	Road test prior to service procedure	No allowance	0 TU		
		Road test after service procedure	No allowance	0 TU		
		Technical diagnosis at dealer's discretion				
		(Refer to Section 2.2.1.2 and Aud: Warranty Online for DADP allowance details)				
	Claim	As per TSB #2014281/4				
	Comment:	S.				

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

TSB 2019334, 91 MMI High System software update (Zug 864 - update) procedure

All part and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

tor.com

©2009 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other interactual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or se posted to other sites, without the prior expressed written permission of the prolisher.

http://www.smartp.brc.com

http://www.smartpDFCreator.com

http://www.SmartpDFCreator.com