

VAG-COM
Windows Based VAG/VAS Emulator
Version: Release 409.1-US
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000

Self-Diagnosis Log
Sunday, 14 February 2016, 15:41:54

VIN Number: TRUSX28N511044626 License Plate: JAMES
Mileage: 151086 Repair Order: 00000001

Chassis Type: 8N - Audi TT
Scan: 01,02,03,08,15,17,22,35,37,45,54,55,56

Address 01: Engine

Controller: 8N0 906 018 L
Component: 1.8L R4/5VT G 0003
Coding: 07500
Shop #: WSC 01236
TRUSX28N511044626 AUZ5Z0A4072036

3 Faults Found:

17608 - Boost Pressure Control Valve (N249): Mechanical Malfunction
P1200 - 35-00 - -
17544 - Fuel Trim: Bank 1 (Add): System too Lean
P1136 - 35-00 - -
16947 - System Voltage Too High
P0563 - 35-10 - - - Intermittent
Readiness: 0010 1001

Address 03: ABS Brakes

Controller: 8N0 907 379 D
Component: ESP 20 CAN V006
Coding: 23049
Shop #: WSC 01236

5 Faults Found:

01542 - Yaw Rate Sensor (G202)
57-00 - Electric Circuit Failure
00668 - Supply Voltage Terminal 30
16-10 - Signal Outside Specifications - Intermittent
01130 - ABS Operation
27-10 - Implausible Signal - Intermittent
01542 - Yaw Rate Sensor (G202)
27-10 - Implausible Signal - Intermittent
00812 - Brake Pressure Release Solenoid (F84)
35-10 - - - Intermittent

VIN Number: TRUSX28N511044626 License Plate: JAMES

Address 08: Auto HVAC

Controller: 8N0 820 043 A
Component: TT-KLIMAVOLLAUTOMAT D03
Coding: 00140
Shop #: WSC 01236

2 Faults Found:

- 01274 - Air Flow Flap Positioning Motor (V71)
 - 41-10 - Blocked or No Voltage - Intermittent
- 00604 - Potentiometer Positioning Motor for Air Flow Flap (G113)
 - 30-00 - Open or Short to B+

Skipping Address 15-Airbags

Address 17: Instruments

Controller: 8N1 920 930 J
Component: KOMBI+WEGFAHRS. M73 D56
Coding: 02244
Shop #: WSC 05127
TRUSX28N511044626 AUZ5Z0A4072036

No fault code found.

Address 35: Centr. Locks

Controller: 8N8 962 267 A
Component: Central Lock/Alarm D05
Coding: 15884
Shop #: WSC 01236

2 Faults Found:

- 01371 - Alarm triggered by Door Contact Switch: Driver's Side
 - 35-00 - -
- 01557 - Contact Switch in Locking Cyl: Driver Side: Open (F241)
 - 29-10 - Short to Ground - Intermittent

Address 45: Inter. Monitor

Controller: 8N8 951 177
Component: Innenraumueberw. D09
Coding: 00001
Shop #: WSC 00000

2 Faults Found:

- 01463 - Alarm triggered by Sensor for anti-theft alarm System
 - 35-00 - -
 - 01462 - Anti-theft alarm ultra sonic Sensor (G209)
 - 53-10 - Supply Voltage Too Low - Intermittent
-

VAG-COM
Self-Diagnosis Log
Sunday, 14 February 2016, 15:41:54
Page 3

VIN Number: TRUSX28N511044626 License Plate: JAMES

Address 55: Xenon Range
Controller: 4B0 907 357
Component: LEUCHTWEITEREGLER D004
Coding: 00009
Shop #: WSC 01236
No fault code found.

Address 56: Radio
Controller: 8N0 035 186 A
Component: Radio D05
Coding: 00517
Shop #: WSC 01236
No fault code found.

End -----