From:	Slatner, Matthew
To:	brian
Subject:	ECU Flash and Driveability
Date:	Tuesday, September 13, 2011 5:56:15 PM

Brian,

As I mentioned on the phone, I've always had surging between 3,000 and 4,000 RPM when 1/4 to 1/2 on the thottle. At one point I mentioned it to Jared and he indicated he hadn't heard of anything like it... it's been a while since I last spoke with him on the issue. West Broad Audi said they felt it but there was nothing they could do and was the "nature of the beast". Not exactly what I wanted to hear so I've been dealing with it for over 23,000 miles with no resolution... hopefully you guys can figure it out now.

--
Thanks!
Matt Slatner