# AUDI A6 3.0 TDI ACTUATOR (TURBO) - Part No: 059147725 / 59001107011

## Trade Price: **£250.00**

(Excludes VAT @ 20%)

- 
- Return Shipping: £8.90 | See all details
- Turn Around: 3-5 working days
- Programming: | See details
- To get this price you will need to send us your faulty unit which we will rebuild and send back to you with a lifetime warranty | Full details

Payment:

Part Numbers:
VM No: 059147725 / 059145702S / 059145725E / 059145725A / 059145715F / 059145702T / 059145715E

OEM No: 59001107011

Vehicle Details:
Make: AUDI, Model: A6, Engine Size: 3.0 , Spec: TDI, Year: 2006 - 2009

Common Faults:
This Turbo actuator for the Audi A6 can have problems of the actuator sticking and not moving correctly and can show fault codes of "19804" Control circuit for the controller for the turbo charger 1 Code "J724" P3348-004 electrical malfunction. If I purchase this will it cure my fault?
Warranty:
Lifetime Warranty*, unlimited mileage

## Customer reviews for this product

Used our products or services — Write a review
No reviews have been submitted.
Product Code:TUA176876

### Categories

- ECU testing
- ABS Pump Module's
- Throttle Bodies
- Dashboards
- Power Steering
- Gearbox ECU
- Diesel Pumps
- OBD II Fault Codes
- ECU Explained

### Common ECU Faults

- Alfa Romeo
- Audi
- BMW
- Citroen
- Daewoo

Fiat
Ford
Honda
Hyundai
Isuzu
Jaguar
Land Rover
Lexus
Mazda
Mercedes
MINI
Mitsubishi
Nissan
Peugeot
Proton
Renault
Rover
Saab
Seat
Skoda
Suzuki
Toyota
Vauxhall
VW
Volvo


Copyright © 2015 ECU Testing ltd. All Rights Reserved.
• Change cookie settings Find out more about cookies

## Cookie Policy

The cookie settings on this website are set to "allow all cookies" to give you the very best experience. If you continue without changing these settings, you consent to this - but if you want, you can change your settings at any time at the bottom of this page.
Find out more about cookies

ecutesting.com