

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64  
VCDS Version: Release 18.2.1(x64) Data version: 20180518 DS287.1  
www.Ross-Tech.com

Dealer/Shop Name:  
Workshop Code: 000 00000 000000

Self-Diagnosis Log  
Friday, 31, August, 2018, 15:37:05:20387

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T  
Mileage: 93620km-58172mi Repair Order: 31 AUG 18

Chassis Type: 7L (6N0)  
Scan: 01 02 03 05 08 09 15 16 17 19 22 34 46 55 56 68 76

VIN: WVGZZZ7LZ7D068231 Mileage: 93620km-58172miles

01-Engine -- Status: OK 0000  
02-Auto Trans -- Status: OK 0000  
03-ABS Brakes -- Status: Malfunction 0010  
04-Steering Angle -- Status: OK 0000  
05-Acc/Start Auth. -- Status: Malfunction 0010  
08-Auto HVAC -- Status: Malfunction 0010  
09-Cent. Elect. -- Status: Malfunction 0010  
15-Airbags -- Status: Malfunction 0010  
16-Steering wheel -- Status: OK 0000  
17-Instruments -- Status: Malfunction 0010  
19-CAN Gateway -- Status: Malfunction 0010  
22-AWD -- Status: Malfunction 0010  
34-Level Control -- Status: Malfunction 0010  
42-Door Elect, Driver -- Status: Malfunction 0010  
46-Central Conv. -- Status: OK 0000  
52-Door Elect, Pass. -- Status: Malfunction 0010  
55-Headlight Range -- Status: OK 0000  
56-Radio -- Status: Cannot be reached 1100  
62-Door, Rear Left -- Status: Malfunction 0010  
68-Wiper Electr. -- Status: OK 0000  
72-Door, Rear Right -- Status: Malfunction 0010  
76-Park Assist -- Status: OK 0000

-----  
Address 01: Engine Labels: . 079-907-560-BAR.clb  
Part No SW: 7L0 907 560 A HW: 7L0 907 560  
Component: 4.2l V8/4V 0030  
Revision: 75H04--- Serial number: VWX3Z0F6536655  
Coding: 04210003590F0560  
Shop #: WSC 31414 790 00001  
VCID: 2F6D7640BD52EF3C8E-515E

No fault code found.  
Readiness: 0110 1101  
-----

VCDS  
Self-Diagnosis Log  
Friday, 31, August, 2018, 15:37:05:20387  
Page 2

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 02: Auto Trans Labels: 09D-927-750.clb  
Part No SW: 09D 927 750 CS HW: 09D 927 750 CS  
Component: AL 750 6A 0993  
Revision: 00H61000 Serial number:  
Coding: 0012650  
Shop #: WSC 31414 790 00001  
VCID: 0109E0F85B46A94C28-515E

No fault code found.

-----  
Address 03: ABS Brakes Labels: 7L0-907-379-MK25E1.clb  
Part No SW: 7L0 907 379 K HW: 7L0 907 379 K  
Component: ESP ALLRAD MK25E1 0302  
Revision: 00H53001  
Coding: 0008578  
Shop #: WSC 31414 790 00001  
VCID: 418920F81CC6694C68-8014

1 Fault Found:

01826 - Sensor for Steering Angle (G85); Supply Voltage Terminal 30  
000 - -

Freeze Frame:

Fault Status: 01100000  
Fault Priority: 2  
Fault Frequency: 1  
Reset counter: 201  
Mileage: 93622 km  
Time Indication: 0  
Date: 2018.08.31  
Time: 15:33:52

Freeze Frame:

Count: 128  
Count: 12545  
Count: 294  
Count: 1

-----

VCDS  
Self-Diagnosis Log  
Friday, 31, August, 2018, 15:37:05:20387  
Page 3

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 05: Acc/Start Auth. Labels: None  
Part No SW: 7L0 909 137 B HW: 5WK 485 17  
Component: 21 Kessy 6840  
Revision: 68406418 Serial number: VWX3Z0F6536655  
Coding: 0155880  
Shop #: WSC 31414 790 00001  
VCID: 326B7F34A960C2D4E1-8066

Subsystem 1 - Part No: XXXXXXXXXXXX  
Component: ELV XXXX

No fault code found.

-----  
Address 08: Auto HVAC Labels: 7L6-907-040.clb  
Part No: 7L6 907 040 AD  
Component: CLIMAtronic R/L 4326  
Coding: 0020530  
Shop #: WSC 31414 790 00001  
VCID: 72EBBF3469E082D421-8026

No fault code found.

-----  
Address 09: Cent. Elect. Labels: 7Lx-937-049-V2.clb  
Part No SW: 7L6 937 049 AA HW: 7L6 937 049 AA  
Component: J519 1801  
Revision: -0004--- Serial number: -----  
Coding: 680004003B261C000000000000000000  
Shop #: WSC 31414 790 00001  
VCID: 7BF592103EAAC39C72-802E

No fault code found.

-----  
Address 15: Airbags Labels: 7L0-959-655.lbl  
Part No SW: 7L0 959 655 HW: 7L0 959 655  
Component: J234 2Y VW8T 0250  
Revision: 92011025 Serial number: 0039P000HVKJ  
Coding: 0012889  
Shop #: WSC 31414 790 00001  
VCID: 7AFB97143190FA9469-802E

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Friday, 31, August, 2018, 15:37:05:20387  
Page 4

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 16: Steering wheel Labels: 7L6-953-549.lbl  
Part No: 7L6 953 549 F  
Component: Lenksaeulenmodul 3501  
Coding: 0000011  
Shop #: WSC 31414 790 00001  
VCID: 428B2FF419C0725471-8016

No fault code found.

-----  
Address 17: Instruments Labels: 7L6-920-xxx-7L6.lbl  
Part No SW: 7L6 920 885 H HW: 7L6 920 885 H  
Component: J0285 KOMBI-INST. 7018  
Revision: KHH06X60  
Coding: 0007501  
Shop #: WSC 77100 981 115492  
VCID: 418920F818C6694C68-8014

No fault code found.

-----  
Address 19: CAN Gateway Labels: . 6N0-909-901-7L.clb  
Part No SW: 6N0 909 901 HW: 7L6 920 885 H  
Component: J533 GW-K-CAN TP20 7018  
Coding: 7FE2E78940046003  
Shop #: WSC 77100 981 115492  
VCID: 70EFB53C63ECB0C4D7-8024

No fault code found.

-----  
Address 22: AWD Labels: None  
Part No: 0AD 927 755 BE  
Component: TRANSFERCASE 0119  
Shop #: WSC 00000 000 00000  
VCID: 7F0D66002DB2DFBC5E-515E

No fault code found.

-----  
Address 34: Level Control Labels: 7Lx-907-553-34.clb  
Part No: 7L0 907 553 G  
Component: LUFTFDR.-CDC- 3C3P1 3112  
Coding: 0015521  
Shop #: WSC 31414 790 00001  
VCID: 377D4E20420227FCD6-8062

1 Fault Found:  
00778 - Steering Angle Sensor (G85)  
000 - -

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 46: Central Conv. Labels: 7L0-959-933.lbl  
Part No: 7L6 959 933  
Component: 10 HSG 7124  
Coding: 0000069  
Shop #: WSC 31414 790 00001  
VCID: 7F0D66002DB2DFBC5E-4B00

Subsystem 1 - Part No: 7L0 959 701 S  
Component: Tuersteuergeraet FS 6302

Subsystem 2 - Part No: 7L0 959 702 S  
Component: Tuersteuergeraet BF 6302

Subsystem 3 - Part No: 7L0 959 703 D  
Component: Tuersteuergeraet HL 0201

Subsystem 4 - Part No: 7L0 959 704 D  
Component: Tuersteuergeraet HR 0201

Subsystem 5 - Part No: 7L0 907 719 A  
Component: Neigungssensor 0020

Subsystem 6 - Part No: 7L6 951 171 B  
Component: Innenraumsensor 0020

No fault code found.

-----  
Address 55: Headlight Range Labels: 7L6-907-357-A.lbl  
Part No SW: 7L6 907 357 A HW: 7L6 907 357 A  
Component: AFS-Steuergeraet X014  
Revision: H01 Serial number:  
Coding: 1288451  
Shop #: WSC 31414 790 00001  
VCID: 397948187416318C20-806C

Subsystem 1 - Part No: 7L6 941 329 B Labels: 3D0-941-329.CLB  
Component: AFS-Lst.-Modul 1 X008  
Coding: 00000019

Subsystem 2 - Part No: 7L6 941 329B Labels: 3D0-941-329.CLB  
Component: AFS-Lst.-Modul r X008  
Coding: 00000019

No fault code found.

-----  
Address 56: Radio  
Cannot be reached  
-----

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 68: Wiper Electr. Labels: 7L0-955-119-V2.clb  
Part No: 7L6 955 119 A  
Component: J400\_\_ Front Wiper 5101  
Coding: 0000343  
Shop #: WSC 31414 790 00001  
VCID: 387F4D1C4B1C2884DF-806C

Subsystem 2 - Part No: 1K0 955 559 AB Labels: 1K0-955-559-AF.CLB  
Component: RLS 310107 020 0105  
Coding: 00733221  
Shop #: WSC 31414

No fault code found.

-----  
Address 76: Park Assist Labels: Redir Fail!  
Part No: 7L0 919 283 F  
Component: 0D Einparkhilfe 1107  
Shop #: WSC 00000 000 00000  
VCID: 397948187416318C20-806C

No fault code found.

End----- (Elapsed Time: 03:26) -----