

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64
VCDS Version: Release 18.2.1(x64) Data version: 20180518 DS287.1
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Friday, 31, August, 2018, 15:29:26:20387

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T
Mileage: 93620km-58172mi Repair Order: 31 AUG 18

Chassis Type: 7L (6N0)
Scan: 01 02 03 05 08 09 15 16 17 19 22 34 46 55 56 68 76

VIN: WVGZZZ7LZ7D068231 Mileage: 93620km-58172miles

01-Engine -- Status: Malfunction 0010
02-Auto Trans -- Status: OK 0000
03-ABS Brakes -- Status: Malfunction 0010
04-Steering Angle -- Status: OK 0000
05-Acc/Start Auth. -- Status: Malfunction 0010
08-Auto HVAC -- Status: Malfunction 0010
09-Cent. Elect. -- Status: Malfunction 0010
15-Airbags -- Status: Malfunction 0010
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: Malfunction 0010
19-CAN Gateway -- Status: Malfunction 0010
22-AWD -- Status: Malfunction 0010
34-Level Control -- Status: Malfunction 0010
42-Door Elect, Driver -- Status: Malfunction 0010
46-Central Conv. -- Status: OK 0000
52-Door Elect, Pass. -- Status: Malfunction 0010
55-Headlight Range -- Status: OK 0000
56-Radio -- Status: Cannot be reached 1100
62-Door, Rear Left -- Status: Malfunction 0010
68-Wiper Electr. -- Status: OK 0000
72-Door, Rear Right -- Status: Malfunction 0010
76-Park Assist -- Status: OK 0000

VCDS
Self-Diagnosis Log
Friday, 31, August, 2018, 15:29:26:20387
Page 2

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 01: Engine Labels: 079-907-560-BAR.clb
Part No SW: 7L0 907 560 A HW: 7L0 907 560
Component: 4.2l V8/4V 0030
Revision: 75H04--- Serial number: VWX3Z0F6536655
Coding: 04210003590F0560
Shop #: WSC 31414 790 00001
VCID: 2F6D7640BD52EF3C8E-515E

2 Faults Found:

005715 - Please check DTC Memory of ABS Controller
P1653 - 002 - - Intermittent

Freeze Frame:

Fault Status: 00100010
Fault Priority: 0
Fault Frequency: 2
Reset counter: 255
Mileage: 93622 km
Time Indication: 0

Freeze Frame:

RPM: 42 /min
Load: 100.0 %
Speed: 0.0 km/h
Temperature: 34.0°C
Temperature: 24.0°C
Absolute Pres.: 820.0 mbar
Voltage: 6.858 V

000801 - Engine Speed Sensor (G28)
P0321 - 008 - Implausible Signal

Freeze Frame:

Fault Status: 01101000
Fault Priority: 0
Fault Frequency: 1
Reset counter: 255
Mileage: 93622 km
Time Indication: 0
Date: 2018.08.31
Time: 15:22:42

Freeze Frame:

RPM: 195 /min
Load: 0.0 %
Speed: 0.0 km/h
Temperature: 29.0°C
Temperature: 20.0°C
Absolute Pres.: 810.0 mbar
Voltage: 12.446 V

Readiness: 0110 1101

VCDS
Self-Diagnosis Log
Friday, 31, August, 2018, 15:29:26:20387
Page 3

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 02: Auto Trans Labels: 09D-927-750.clb
Part No SW: 09D 927 750 CS HW: 09D 927 750 CS
Component: AL 750 6A 0993
Revision: 00H61000 Serial number:
Coding: 0012650
Shop #: WSC 31414 790 00001
VCID: 0109E0F85B46A94C28-5140

No fault code found.

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 03: ABS Brakes Labels: 7L0-907-379-MK25E1.clb
Part No SW: 7L0 907 379 K HW: 7L0 907 379 K
Component: ESP ALLRAD MK25E1 0302
Revision: 00H53001
Coding: 0008578
Shop #: WSC 31414 790 00001
VCID: 418920F81CC6694C68-8014

2 Faults Found:

00668 - Supply Voltage Terminal 30
002 - Lower Limit Exceeded - Intermittent
Freeze Frame:
Fault Status: 00100010
Fault Priority: 2
Fault Frequency: 2
Reset counter: 201
Mileage: 93622 km
Time Indication: 0
Date: 2018.08.06
Time: 20:26:38

Freeze Frame:
Count: 64
Count: 14593
Count: 128
Count: 1

01826 - Sensor for Steering Angle (G85); Supply Voltage Terminal 30
000 - -
Freeze Frame:
Fault Status: 01100000
Fault Priority: 2
Fault Frequency: 92
Reset counter: 201
Mileage: 93622 km
Time Indication: 0
Date: 2018.07.29
Time: 14:25:20

Freeze Frame:
Count: 128
Count: 13057
Count: 294
Count: 1

VCDS
Self-Diagnosis Log
Friday, 31, August, 2018, 15:29:26:20387
Page 5

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 05: Acc/Start Auth. Labels: None
Part No SW: 7L0 909 137 B HW: 5WK 485 17
Component: 21 Kessy 6840
Revision: 68406418 Serial number: VWX3Z0F6536655
Coding: 0155880
Shop #: WSC 31414 790 00001
VCID: 326B7F34A960C2D4E1-8066

Subsystem 1 - Part No: XXXXXXXXXXXX
Component: ELV XXXX

2 Faults Found:
00087 - Terminal 30 for Starting Relevant Consumers
009 - Open or Short to Ground - Intermittent
00668 - Supply Voltage Terminal 30
009 - Open or Short to Ground - Intermittent

Address 08: Auto HVAC Labels: 7L6-907-040.clb
Part No: 7L6 907 040 AD
Component: CLIMAtronic R/L 4326
Coding: 0020530
Shop #: WSC 31414 790 00001
VCID: 72EBBF3469E082D421-8026

1 Fault Found:
00668 - Supply Voltage Terminal 30
002 - Lower Limit Exceeded - Intermittent

Address 09: Cent. Elect. Labels: 7Lx-937-049-V2.clb
Part No SW: 7L6 937 049 AA HW: 7L6 937 049 AA
Component: J519 1801
Revision: -0004--- Serial number: -----
Coding: 680004003B261C000000000000000000
Shop #: WSC 31414 790 00001
VCID: 7BF592103EAAC39C72-802E

1 Fault Found:
01494 - Bulb for Parking Lamps; Left (M1)
011 - Open Circuit - Intermittent

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 15: Airbags Labels: 7L0-959-655.lbl
Part No SW: 7L0 959 655 HW: 7L0 959 655
Component: J234 2Y VW8T 0250
Revision: 92011025 Serial number: 0039P000HVKJ
Coding: 0012889
Shop #: WSC 31414 790 00001
VCID: 7AFB97143190FA9469-802E

1 Fault Found:
00532 - Supply Voltage B+
002 - Lower Limit Exceeded - Intermittent
Freeze Frame:
Fault Status: 00100010
Fault Priority: 2
Fault Frequency: 1
Reset counter: 255
Mileage: 93622 km
Time Indication: 0
Date: 2018.08.06
Time: 20:27:01

Address 16: Steering wheel Labels: 7L6-953-549.lbl
Part No: 7L6 953 549 F
Component: Lenksaeulenmodul 3501
Coding: 0000011
Shop #: WSC 31414 790 00001
VCID: 428B2FF419C0725471-8016

No fault code found.

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 17: Instruments Labels: 7L6-920-xxx-7L6.lbl
Part No SW: 7L6 920 885 H HW: 7L6 920 885 H
Component: J0285 KOMBI-INST. 7018
Revision: KHH06X60
Coding: 0007501
Shop #: WSC 77100 981 115492
VCID: 418920F818C6694C68-8014

4 Faults Found:

- 01304 - Radio
004 - No Signal/Communication
Freeze Frame:
Fault Status: 01100100
Fault Priority: 2
Fault Frequency: 1
Reset counter: 255
Mileage: 93622 km
Time Indication: 0
Date: 2018.07.29
Time: 14:23:35
- 00771 - Fuel Level Sensor (G)
010 - Open or Short to Plus - Intermittent
Freeze Frame:
Fault Status: 00101010
Fault Priority: 2
Fault Frequency: 1
Reset counter: 241
Mileage: 93622 km
Time Indication: 0
Date: 2018.08.03
Time: 19:08:07
- 00438 - Fuel Supply Sensor 2 (G169)
010 - Open or Short to Plus - Intermittent
Freeze Frame:
Fault Status: 00101010
Fault Priority: 2
Fault Frequency: 1
Reset counter: 241
Mileage: 93622 km
Time Indication: 0
Date: 2018.08.03
Time: 19:14:56
- 00446 - Function Limitation due to Under-Voltage
002 - Lower Limit Exceeded - Intermittent
Freeze Frame:
Fault Status: 00100010
Fault Priority: 2
Fault Frequency: 30
Reset counter: 241

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Mileage: 93622 km
Time Indication: 0
Date: 2018.08.06
Time: 20:12:05

Address 19: CAN Gateway Labels: 6N0-909-901-7L.clb
Part No SW: 6N0 909 901 HW: 7L6 920 885 H
Component: J533 GW-K-CAN TP20 7018
Coding: 7FE2E78940046003
Shop #: WSC 77100 981 115492
VCID: 70EFB53C63ECB0C4D7-8024

2 Faults Found:

01304 - Radio

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100
Fault Priority: 2
Fault Frequency: 1
Reset counter: 255
Mileage: 93622 km
Time Indication: 0
Date: 2018.07.29
Time: 14:23:35

00446 - Function Limitation due to Under-Voltage

002 - Lower Limit Exceeded - Intermittent

Freeze Frame:

Fault Status: 00100010
Fault Priority: 2
Fault Frequency: 30
Reset counter: 241
Mileage: 93622 km
Time Indication: 0
Date: 2018.08.06
Time: 20:12:05

Address 22: AWD Labels: None

Part No: 0AD 927 755 BE
Component: TRANSFERCASE 0119
Shop #: WSC 00000 000 00000
VCID: 7F0D66002DB2DFBC5E-5140

1 Fault Found:

00532 - Supply Voltage B+

002 - Lower Limit Exceeded - Intermittent

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 34: Level Control Labels: 7Lx-907-553-34.clb
Part No: 7L0 907 553 G
Component: LUFTFDR.-CDC- 3C3P1 3112
Coding: 0015521
Shop #: WSC 31414 790 00001
VCID: 377D4E20420227FCD6-8062

3 Faults Found:

01772 - Signal from Level Control Pressure Sensor (G291)
009 - Open or Short to Ground - Intermittent
01598 - Drive Battery Voltage
002 - Lower Limit Exceeded - Intermittent
00778 - Steering Angle Sensor (G85)
000 - -

Address 46: Central Conv. Labels: 7L0-959-933.lbl
Part No: 7L6 959 933
Component: 10 HSG 7124
Coding: 0000069
Shop #: WSC 31414 790 00001
VCID: 7F0D66002DB2DFBC5E-4B00

Subsystem 1 - Part No: 7L0 959 701 S
Component: Tuersteuergeraet FS 6302

Subsystem 2 - Part No: 7L0 959 702 S
Component: Tuersteuergeraet BF 6302

Subsystem 3 - Part No: 7L0 959 703 D
Component: Tuersteuergeraet HL 0201

Subsystem 4 - Part No: 7L0 959 704 D
Component: Tuersteuergeraet HR 0201

Subsystem 5 - Part No: 7L0 907 719 A
Component: Neigungssensor 0020

Subsystem 6 - Part No: 7L6 951 171 B
Component: Innenraumsensor 0020

4 Faults Found:

01811 - Supply Voltage for Door Controller; Drivers Side (J386)
002 - Lower Limit Exceeded - Intermittent
01812 - Supply Voltage for Door Controller; Pass. Side (J387)
002 - Lower Limit Exceeded - Intermittent
01333 - Door Control Module; Rear Left (J388)
002 - Lower Limit Exceeded - Intermittent
01334 - Door Control Module; Rear Right (J389)
002 - Lower Limit Exceeded - Intermittent

VIN: WVGZZZ7LZ7D068231 License Plate: KBZ 880T

Address 55: Headlight Range Labels: 7L6-907-357-A.lbl
Part No SW: 7L6 907 357 A HW: 7L6 907 357 A
Component: AFS-Steuergeraet X014
Revision: H01 Serial number:
Coding: 1288451
Shop #: WSC 31414 790 00001
VCID: 397948187416318C20-806C

Subsystem 1 - Part No: 7L6 941 329 B Labels: 3D0-941-329.CLB
Component: AFS-Lst.-Modul 1 X008
Coding: 00000019

Subsystem 2 - Part No: 7L6 941 329 B Labels: 3D0-941-329.CLB
Component: AFS-Lst.-Modul r X008
Coding: 00000019

No fault code found.

Address 56: Radio
Cannot be reached

Address 68: Wiper Electr. Labels: 7L0-955-119-V2.clb
Part No: 7L6 955 119 A
Component: J400__ Front Wiper 5101
Coding: 0000343
Shop #: WSC 31414 790 00001
VCID: 387F4D1C4B1C2884DF-806C

Subsystem 2 - Part No: 1K0 955 559 AB Labels: 1K0-955-559-AF.CLB
Component: RLS 310107 020 0105
Coding: 00733221
Shop #: WSC 31414

No fault code found.

Address 76: Park Assist Labels: Redir Fail!
Part No: 7L0 919 283 F
Component: 0D Einparkhilfe 1107
Shop #: WSC 00000 000 00000
VCID: 397948187416318C20-806C

No fault code found.

End----- (Elapsed Time: 03:07)-----