ator.com Technical Service Bulletin

No.: 2017729/2

00 Electrical components malfunctioning after windows have been Attp://www.Srr tinted

Release date: Nov 17, 2008

Transactio.

Condition

ISION HISTORY

| Revision | Date | Purpose |
|----------|------|---------------------------------------|
| 2 | - | Revised Title to include Repair Group |

Various electrical components malfunctioning.

Water ingress into trunk area during the application of window tint.

Technical Background

Vehicles are designed to prevent water from entering the interior cabin from the outside. To ensure a secure installation of interior components (trim and accessory pieces), holes for fasteners are strategically placed in interior surfaces. During application of window tint film, water may enter trunk area through these openings, damaging electrical components located in the trunk below the hat shelf and in the wheel well area. Electrical components in these areas must be removed or protected during application of window tint film.

Production Solution

Not applicable.

Service

http://w

- below the hat shelf and the windows are tinted, check if the failure occurred shortly after the window tint was installed. Inspect the control module and wiring connections for signs of water damage. 1.
- 2.
- Also inform any vendors with which your Dealership may conduct business about the 3. http://www.c content of this bulletin.

Warranty

eator.com This damage is due to butside influence and is not covered by any Audi warranty.

Additional Information

http://www.smaitp.fcreator.com

the protocol All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2008 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inconts affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these , rior e) materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

http://www.smartpDFCreator.com