



Technical Service Bulletin

Electrical failures or component malfunctions - Wire harness repairs

97 07 08 July 2, 2007 2014745/1

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2007	All	Not Applicable
A8	2007	All	
Audi Q7	2007	All	

Condition

Various electrical failures or malfunctions of components. Areas of concern are powertrain, drivetrain, chassis, body/equipment, vehicle electrical system, and heating/ventilation/air conditioning.

Technical Background

In cases where the vehicle wiring is the cause of component failure due to wire(s) being cut, pinched, damaged, improperly routed, etc., and/or terminals, connectors or connections that are loose, broken, not fully engaged, etc., please see the *Service* section below.

Production Solution

Not applicable.

Service

In order to improve the quality of Audi electrical systems, please create a Technical Assistance Center contact.

Along with providing general information, please include the following detailed diagnostic information:

- Specific circuit and wire(s) that are affected.
- Terminal(s), connector(s), and/or connection(s) that are affected.
- Digital photos showing the affected electrical components.

Then call the Technical Assistance Center for further direction.

Warranty

This TSB is informational only and not applicable to any Audi warranty.



Technical Service Bulletin

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.