



**Audi**

**Important!**

Please give copies to  
all your Audi Technicians

# Technical Bulletin

---

Subject: **Emergency Flasher Switch -E229-, Light Flickers**

Group: **94**

Number: **05-03**

Model(s): **A6**

2005 prior to VIN: **4F\_5N079810** Date: **Mar. 3, 2005**

---

## Condition

The Emergency Flasher switch -E229- internal light flickers intermittently (most noticeable when interior lights are dimmed to lowest setting).

## Service

DO NOT replace Emergency Flasher switch -E229- or vehicle electrical system Control Module -J519-.

Please contact the Audi Helpline at 1(800) 388-2834 (for further assistance).



### Tip:

*No Diagnostic time will be allowed under Warranty.*