

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised Title to include Repair Group

Maintenance Service Intervals (time and mileage adaptation values) must be reset as a part of the regularly scheduled maintenance.

Brand CD 10.53 includes a new procedure to reset the service interval cluster warning, mileage and day service interval for the TT (A2), A3 (AB2), A6 (C6), A8 (D3), Audi Q7, R8 and any models produced after model year 2008. The new procedure for the A4 (B7) and Cabriolet (B7) will be included first in Brand CD 10.54.

Technical Background

The mileage interval settings must be changed from 5,000 miles to 10,000 miles and/or the time interval settings from 180 days to 365 days at the first maintenance. If these settings are not changed, the Service Reminder interval warning in the cluster will activate at the odometer reading of approximately 10,000 miles or 180 days from the first service. This will cause the customer to unnecessarily return to have the warning turned off.

Production Solution

Not applicable.

Service

R8, TT (A2), A3 (AB2), A6 (C6), A8 (D3), Audi Q7 and all models produced after Model Year 2008

Reset the Service Reminder and the mileage and day interval parameters in one plan, by selecting in the testers (Minimum Brand CD Level 10.53): GF >> Service Work >> J285 - Instr. Cluster, ext.service intervals resetting.

NOTE: The A4 and Cabriolet (B7) will be able to be set using this procedure starting with Brand CD 10.54.

For all older models

If a vehicle comes in at an interval when no service is required (e.g. 10,000 miles, or 15,000 miles) with the service reminder on, the service reminder must be reset along with the mileage and day interval adaptation parameters. These parameters must be set to the appropriate intervals according to the appropriate Audi Service Circular for that vehicle.

This can be carried out in the Guided Functions >> Service Work section.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

All part and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information.

©2008 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.