

VCDS

Windows Based VAG/VAS Emulator Running on Windows 7 x64
VCDS Version: Release 17.1.1(x64) Data version: 20170106 DS267.0
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Wednesday, 18, January, 2017, 18:12:36:01949

VIN: WAUMV44E17N015584 License Plate:
Mileage: 167620km-104154mi Repair Order:

Chassis Type: 4E (4L0)

Scan: 01 02 03 05 06 07 08 09 0E 0F 15 16 17 19 1E 34 36 37 38 42
46 47 4F 52 53 55 56 61 62 65 67 6C 72 76 77

VIN: WAUMV44E17N015584 Mileage: 167620km-104154miles

00-Steering Angle Sensor -- Status: OK 0000
01-Engine -- Status: Malfunction 0010
02-Auto Trans -- Status: OK 0000
03-ABS Brakes -- Status: Malfunction 0010
05-Acc/Start Auth. -- Status: Malfunction 0010
06-Seat Mem. Pass -- Status: OK 0000
07-Control Head -- Status: OK 0000
08-Auto HVAC -- Status: OK 0000
09-Cent. Elect. -- Status: Malfunction 0010
0E-Media Player 1 -- Status: Malfunction 0010
0F-Digital Radio -- Status: Malfunction 0010
15-Airbags -- Status: OK 0000
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
19-CAN Gateway -- Status: OK 0000
1E-Media Player 2 -- Status: Malfunction 0010
34-Level Control -- Status: Malfunction 0010
36-Seat Mem. Drvr -- Status: OK 0000
37-Navigation -- Status: OK 0000
38-Roof Electronics -- Status: OK 0000
42-Door Elect, Driver -- Status: Malfunction 0010
46-Central Conv. -- Status: Malfunction 0010
47-Sound System -- Status: OK 0000
4F-Centr. Electr. II -- Status: OK 0000
52-Door Elect, Pass. -- Status: Malfunction 0010
53-Parking Brake -- Status: Malfunction 0010
55-Headlight Range -- Status: Malfunction 0010
56-Radio -- Status: OK 0000
61-Battery Regul. -- Status: OK 0000
62-Door, Rear Left -- Status: Malfunction 0010
65-Tire Pressure -- Status: Malfunction 0010
67-Voice Control -- Status: OK 0000
6C-Back-up Cam. -- Status: Malfunction 0010
72-Door, Rear Right -- Status: Malfunction 0010
76-Park Assist -- Status: OK 0000
77-Telephone -- Status: OK 0000

VCDS
Self-Diagnosis Log
Wednesday, 18, January, 2017, 18:12:36:01949
Page 2

VIN: WAUMV44E17N015584 License Plate:

Address 01: Engine Labels: 079-907-560-BVJ.clb
Part No SW: 4E1 910 560 A HW: 4E1 907 560
Component: 4.2l V8/4V 0040
Revision: 71H21--- Serial number: AUX3Z0G0715056
Coding: 01060009190F0120
Shop #: WSC 25169 444 84354
VCID: 204F8E7DF3C47E41F5-8074

1 Fault Found:

005715 - Please check DTC Memory of ABS Controller

P1653 - 008 -

Freeze Frame:

Fault Status: 01101000
Fault Priority: 0
Fault Frequency: 2
Reset counter: 255
Mileage: 167626 km
Time Indication: 0
Date: 2017.01.18
Time: 18:07:35

Freeze Frame:

RPM: 0 /min
Load: 0.0 %
Speed: 0.0 km/h
Temperature: 42.0°C
Temperature: 39.0°C
Absolute Pres.: 840.0 mbar
Voltage: 11.430 V

Readiness: 0110 1101

Address 02: Auto Trans Labels: 09L-927-760.lbl
Part No SW: 4E1 910 156 C HW: 09L 927 156 A
Component: AG6 09L 4,2lFSI USA 0030
Revision: --H01--- Serial number: 4281415
Coding: 0000002
Shop #: WSC 02313 785 00200
VCID: 23458171E2D26559E8-8076

No fault code found.

VIN: WAUMV44E17N015584 License Plate:

Address 03: ABS Brakes Labels: 4E0-910-517.lbl
Part No SW: 4E0 910 517 B HW: 4E0 614 517 BC
Component: ESP 5.7 allrad H46 0510
Coding: 0007597
Shop #: WSC 02313 000 00000
VCID: 224B8475FDC86C51E3-8076

1 Fault Found:
01826 - Sensor for Steering Angle (G85); Supply Voltage Terminal 30
000 - -

Address 05: Acc/Start Auth. Labels: 4E0-910-131.lbl
Part No SW: 4E0 910 131 HW: 4E0 909 131 L
Component: FBS AUDID3 H10 0190
Revision: 01904910 Serial number: AUX3Z0G0715056
Coding: 0410624
Shop #: WSC 02311 785 00200
VCID: 58BFE69DEB14F681CD-800C

Subsystem 1 - Part No: XXXXXXXXXXXX
Component: ELV XXXX

1 Fault Found:
00668 - Supply Voltage Terminal 30
002 - Lower Limit Exceeded - Intermittent
Freeze Frame:
Fault Status: 00100010
Fault Priority: 2
Fault Frequency: 1
Reset counter: 170
Mileage: 167616 km
Time Indication: 0
Date: 2017.01.18
Time: 17:24:40

Address 06: Seat Mem. Pass Labels: None
Part No SW: 4E0 910 760 D HW: 4E0 959 760 B
Component: Sitzmemory BFS H02 0010
Revision: 00000000 Serial number: 5DS 008 795-03
Coding: 4071648
Shop #: WSC 02313 785 00200
VCID: 2447826DE7DC626191-8070

No fault code found.

VCDS
Self-Diagnosis Log
Wednesday, 18, January, 2017, 18:12:36:01949
Page 4

VIN: WAUMV44E17N015584 License Plate:

Address 07: Control Head Labels: 4E0-910-7xx-07.lbl
Part No SW: 4E0 910 731 P HW: 4E0 035 729 A
Component: Interfacebox H43 3360
Revision: 00000000 Serial number: 348AL077509320
Coding: 0000003
Shop #: WSC 02313 785 00200
VCID: 2E536045B910D83177-807A

Subsystem 1 - Part No: 4E0 910 611
Component: E0380 BedienteilH01 0040

Subsystem 2 - Serial number: 00000000029718

Subsystem 3 - Serial number: 0127.01.070000000100010070ÿ

Subsystem 4 - Serial number: 010070ÿ

No fault code found.

Address 08: Auto HVAC Labels: None
Part No SW: 4E0 910 043 B HW: 4E0 820 043 H
Component: KLIMAAUTOMAT 017 0450
Revision: 00000032 Serial number: 00000000112833
Coding: 0037313
Shop #: WSC 02311 785 00200
VCID: 1C37BA8DDFAC5AA129-8048

Subsystem 1 - Part No: 4E0 910 772 A
Component: Sitzluefter FS H02 010

Subsystem 2 - Part No: 4E0 910 772 A
Component: Sitzluefter BFS H02 010

Subsystem 3 - Serial number: 898053000

Subsystem 4 - Serial number: HO16012007065A000000000017ÿ†•89

Subsystem 5 - Serial number: 000017ÿ†•898053000 000-SHO

Subsystem 6 - Serial number: 000-SHO15012007065A00000000

Subsystem 7 - Serial number: 65A000000000018ÿ

No fault code found.

VIN: WAUMV44E17N015584 License Plate:

Address 09: Cent. Elect. Labels: 4E0-910-279.lbl
Part No SW: 4E0 910 279 Q HW: 4E1 955 113 C
Component: ILM Fahrer H15 0230
Coding: 0143123
Shop #: WSC 02313 785 00200
VCID: 366348254140E0F13F-8062

Subsystem 1 - Part No: 4E1 910 113 C
Component: Wischer WWS D3 H60 0420
Coding: 00000037
Shop #: WSC 02313

Subsystem 2 - Part No: 4E0 910 557 A Labels: 8K0-955-559.CLB
Component: REGENLICHTSENSORH13 0090
Coding: 00139548
Shop #: WSC 02313

5 Faults Found:

00908 - Control Module for Wiper Motor
004 - No Signal/Communication - Intermittent

Freeze Frame:
Fault Status: 00100100
Fault Priority: 1
Fault Frequency: 1
Reset counter: 170
Mileage: 0 km
Time Indication: 0
Date: 2017.01.18
Time: 00:00:00

01493 - Bulb for Blinkers; Front Left (M5)
010 - Open or Short to Plus

Freeze Frame:
Fault Status: 01101010
Fault Priority: 2
Fault Frequency: 1
Reset counter: 130
Mileage: 167626 km
Time Indication: 0
Date: 2017.01.18
Time: 00:01:00

01497 - Bulb for Blinkers; Front Right (M7)
010 - Open or Short to Plus

Freeze Frame:
Fault Status: 01101010
Fault Priority: 2
Fault Frequency: 1
Reset counter: 130
Mileage: 167626 km
Time Indication: 0
Date: 2017.01.18

VIN: WAUMV44E17N015584 License Plate:

Time: 00:01:00

01498 - Bulb for Parking Lamps; Right (M3)

010 - Open or Short to Plus

Freeze Frame:

Fault Status: 01101010

Fault Priority: 2

Fault Frequency: 1

Reset counter: 130

Mileage: 167626 km

Time Indication: 0

Date: 2017.01.18

Time: 00:01:21

00978 - Lamp for Low Beam; Left (M29)

010 - Open or Short to Plus

Freeze Frame:

Fault Status: 01101010

Fault Priority: 2

Fault Frequency: 1

Reset counter: 130

Mileage: 167626 km

Time Indication: 0

Date: 2017.01.18

Time: 00:01:24

Address 0E: Media Player 1 (R192) Labels: 4E0-035-785.lbl
Part No SW: 4E0 035 785 HW: 4E0 035 785
Component: SG ext.Player H09 0170
Revision: 00000000
VCID: 65C1DF696C665B6946-8030

1 Fault Found:

00532 - Supply Voltage B+

002 - Lower Limit Exceeded - Intermittent

Freeze Frame:

Fault Status: 00100010

Fault Priority: 2

Fault Frequency: 5

Reset counter: 154

Mileage: 163817 km

Time Indication: 0

Date: 2016.11.28

Time: 19:49:56

VIN: WAUMV44E17N015584 License Plate:

Address 0F: Digital Radio Labels: 4E0-910-593-SIR.lbl
Part No SW: 4E0 910 593 H HW: 4E0 035 593 D
Component: SDAR SIRIUS H06 0080
Revision: 00000000 Serial number: AUZ4Z7G0043914
Shop #: WSC 00000 000 00000
VCID: 2C576A4D8F0CAA2159-8078

No fault code found.

Address 15: Airbags Labels: 4E0-910-655-94.lbl
Part No SW: 4E0 910 655 C HW: 4E0 959 655 J
Component: Airbag 9.41 H14 4230
Revision: 91H14423 Serial number: 0037Q0G01KC%
Coding: 0532707
Shop #: WSC 02313 785 00200
VCID: 2643986591E090718F-8072

Subsystem 1 - Part No: 4E0 910 339
Component: BF-Gewichtsens. H01 0030

Subsystem 2 - Serial number: 3J5K6

Subsystem 3 - Serial number: 0001.01.0000H0100000000000ÿ†•63

Subsystem 4 - Serial number: 000000ÿ†•63328RB401F63FAB\$ÿ†•63

Subsystem 5 - Serial number: 63FAB\$ÿ†•63428RB401F64097Lÿ†•63

Subsystem 6 - Serial number: 64097Lÿ†•63528RB401F63F2DZÿ†•63

Subsystem 7 - Serial number: 63F2DZÿ†•63628RB401F63D83Uÿ†•63

Subsystem 8 - Serial number: 63D83Uÿ†•63729RB401D9680EYÿ†•63

Subsystem 9 - Serial number: 9680EYÿ†•63829RB401D967BD1ÿ

Subsystem 10 - Serial number: 967BD1ÿ

No fault code found.

VIN: WAUMV44E17N015584 License Plate:

Address 16: Steering wheel Labels: 4E0-910-549.lbl
Part No SW: 4E0 910 549 HW: 4E0 953 549
Component: Lenksäulenmodul H14 0040
Coding: 0012141
Shop #: WSC 02311 785 00200
VCID: 65C1DF69AC665B6946-8030

Subsystem 1 - Part No: XXXXXXXXXXXX
Component: Lenkradmodul H07 0090

No fault code found.

Address 17: Instruments Labels: 4E0-910-xxx-17.lbl
Part No SW: 4E0 910 951 C HW: 4E0 920 951 C
Component: KOMBIINSTR. VDO H82 0530
Revision: D04 Serial number: AUDID3G0002183
Coding: 0048263
Shop #: WSC 49114 001 1048576
VCID: 25419F69ECE69B6986-8070

No fault code found.

Address 19: CAN Gateway Labels: 4L0-910-468.clb
Part No SW: 4L0 910 468 HW: 4L0 907 468
Component: J533 Gateway H06 0040
Revision: 00H06000 Serial number: 0900B07116801F
Coding: F5D5DF7F707A0E
Shop #: WSC 02313 785 00200
VCID: 6CD7AA4D4F8C6A2119-8038

No fault code found.

VIN: WAUMV44E17N015584 License Plate:

Address 1E: Media Player 2 Labels: 4E0-910-111.lbl
Part No SW: 4E0 910 110 C HW: 4E0 035 110 A
Component: MP3-Changer H44 0350
Revision: 00044000 Serial number: AUZ5ZBG3146375
Shop #: WSC 00000 000 00000
VCID: 183FA69D2B9436810D-804C

1 Fault Found:

02261 - Data Medium

014 - Defective

Freeze Frame:

Fault Status: 01101110

Fault Priority: 7

Fault Frequency: 1

Reset counter: 130

Mileage: 167626 km

Time Indication: 0

Date: 2017.01.18

Time: 18:09:14

Freeze Frame:

Text: 00000000

VIN: WAUMV44E17N015584 License Plate:

Address 34: Level Control Labels: 4E0-910-553.lbl
Part No SW: 4E0 910 553 J HW: 4E0 907 553 F
Component: LUFTFDR.-CDC H06 6310
Coding: 0015510
Shop #: WSC 02313 785 00200
VCID: 2A5B6C5585F8B411AB-807E

2 Faults Found:

01770 - Temperature Sensor for Level Control Pump/Compressor (G290)

010 - Open or Short to Plus

Freeze Frame:

Fault Status: 11101010
Fault Priority: 4
Fault Frequency: 1
Reset counter: 130
Mileage: 167626 km
Time Indication: 0
Date: 2017.01.18
Time: 18:08:25

01397 - Venting Solenoid for Level Control (N111)

009 - Open or Short to Ground

Freeze Frame:

Fault Status: 11101001
Fault Priority: 2
Fault Frequency: 1
Reset counter: 130
Mileage: 167626 km
Time Indication: 0
Date: 2017.01.18
Time: 18:08:25

Address 36: Seat Mem. Drvr Labels: None
Part No SW: 4E0 910 760 D HW: 4E0 959 760 B
Component: Sitzmemory FS H03 0010
Revision: 00000000 Serial number: 5DS 008 795-03
Coding: 4063330
Shop #: WSC 27714 002 1048576
VCID: 2447826DE7DC626191-8070

No fault code found.

VIN: WAUMV44E17N015584 License Plate:

Address 37: Navigation Labels: 4E0-910-88x-37.lbl
Part No SW: 4E0 910 888 M HW: 4E0 919 887 L
Component: MNS US H48 1100
Revision: 00000000 Serial number: 381AU077516847
Shop #: WSC 25169 444 54100
VCID: 387F461D4B5416812D-806C

No fault code found.

Address 38: Roof Electronics Labels: 4E0-910-135.lbl
Part No SW: 4E0 910 135 A HW: 4E0 907 135 A
Component: Dachknoten D3 H05 0090
Serial number: 00000813700047
Coding: 0003502
Shop #: WSC 25169 444 58785
VCID: 1D31B789C4B653A9DE-8048

No fault code found.

Address 42: Door Elect, Driver Labels: 4E1-910-802-42.lbl
Part No SW: 4E1 910 802 B HW: 4E1 959 801 D
Component: Türsteuer.FS BRM005 0180
Coding: 0032364
Shop #: WSC 02313 785 00200
VCID: 204F8E7DF3C47E41F5-8074

1 Fault Found:
01308 - Control Module for Roof Electronics (J528)
004 - No Signal/Communication - Intermittent
Freeze Frame:
Fault Status: 00100100
Fault Priority: 4
Fault Frequency: 0
Reset counter: 154
Mileage: 166784 km
Time Indication: 0
Date: 2017.01.10
Time: 00:03:46

VIN: WAUMV44E17N015584 License Plate:

Address 46: Central Conv. Labels: 4E0-910-289.lbl
Part No SW: 4E0 910 289 D HW: 4E0 907 289 D
Component: Komfortgeraet H08 0020
Revision: 00200008 Serial number: W040701230279
Coding: 0048702
Shop #: WSC 02313 785 00200
VCID: 2A5B6C5585F8B411AB-807E

Subsystem 1 - Part No: 4E0 910 853
Component: Heckdeckel P27H08 0090

Subsystem 2 - Part No: 4E0 907 719
Component: Neigungssensor H05 0020

1 Fault Found:

00984 - Left Tail Light (M4)
004 - No Signal/Communication
Freeze Frame:
Fault Status: 01100100
Fault Priority: 3
Fault Frequency: 254
Reset counter: 130
Mileage: 150332 km
Time Indication: 0
Date: 2016.06.09
Time: 05:05:38

Address 47: Sound System Labels: 4E0-910-223.lbl
Part No SW: 4E0 910 223 Q HW: 4E0 035 223 G
Component: DSP-High D3 H03 0110
Revision: PROD 01 Serial number: 00000000002065
Coding: 0000026
Shop #: WSC 02313 785 00200
VCID: 2B5569518A02AD1950-807E

No fault code found.

VIN: WAUMV44E17N015584 License Plate:

Address 4F: Centr. Electr. II Labels: None
Part No SW: 4E0 910 280 A HW: 4E0 907 280 A
Component: ILM Beifahrer H11 0070
Revision: Serial number: 00000000104363
Coding: 0010111
Shop #: WSC 02313 785 00200
VCID: 1E33B085C9B048B1C7-804A

Subsystem 1 - Part No: 4E0 910 511 A
Component: UGDO HL US H04 0050

Subsystem 2 - Serial number: 0253440T19DN05

No fault code found.

Address 52: Door Elect, Pass. Labels: 4E1-910-802-52.lbl
Part No SW: 4E1 910 802 B HW: 4E1 959 802 D
Component: Türsteuer.BF BRM005 0180
Coding: 0032364
Shop #: WSC 02313 785 00200
VCID: 204F8E7DF3C47E41F5-8074

1 Fault Found:
01308 - Control Module for Roof Electronics (J528)
004 - No Signal/Communication - Intermittent
Freeze Frame:
Fault Status: 00100100
Fault Priority: 4
Fault Frequency: 0
Reset counter: 154
Mileage: 166784 km
Time Indication: 0
Date: 2017.01.10
Time: 00:03:46

VIN: WAUMV44E17N015584 License Plate:

Address 53: Parking Brake Labels: 4E0-910-801.clb
Part No SW: 4E0 910 801 D HW: 4E0 907 801 B
Component: EPB A4EC0230 H03 0230
Revision: --H03---
Coding: 0000922
Shop #: WSC 27714 002 1048576
VCID: 204F8E7DF3C47E41F5-8074

1 Fault Found:

02596 - Rear Brake Pads Worn
008 - Implausible Signal

Freeze Frame:

Fault Status: 01111000
Fault Priority: 6
Fault Frequency: 1
Reset counter: 236
Time Indication: 0

Freeze Frame:

Voltage: 8.90 V
Count: 61

VIN: WAUMV44E17N015584 License Plate:

Address 55: Headlight Range Labels: 4F0-910-357.lbl
Part No SW: 4F0 910 357 F HW: 4F0 907 357 F
Component: AFS 1 H01 0020
Revision: 00000001 Serial number:
Coding: 0000018
Shop #: WSC 02313 785 00200
VCID: 2959935980FEBF09A2-807C

Subsystem 1 - Part No: 4F0 941 329 B
Component: AFS-Modul links H02 0020

Subsystem 2 - Part No: 4F0 941 329 B
Component: AFS-Modul rechtsH02 0020

1 Fault Found:

01539 - Headlights Not Adjusted
005 - No or Incorrect Basic Setting / Adaptation - MIL ON
Freeze Frame:
Fault Status: 11100101
Fault Priority: 2
Fault Frequency: 1
Reset counter: 130
Mileage: 167624 km
Time Indication: 0
Date: 2017.01.18
Time: 18:08:26

Address 56: Radio Labels: 4E0-910-541.lbl
Part No SW: 4E0 910 541 Q HW: 4E0 035 541 S
Component: TUNER EU/US/RDW H42 0620
Revision: 00000000 Serial number: 396A\$077558628
Coding: 0000002
Shop #: WSC 02313 785 00200
VCID: 2E536045B910D83177-807A

No fault code found.

VIN: WAUMV44E17N015584 License Plate:

Address 61: Battery Regul. Labels: 4E0-910-181.lbl
Part No SW: 4E0 910 181 C HW: 4E0 915 181 C
Component: J0644 BEM H12 0550
Revision: 00000000 Serial number: 00000000028838
Shop #: WSC 25169 444 54100
VCID: 204F8E7DF3C47E41F5-8074

Subsystem 1 - Part No: 000 915 105 DL
Component: von VA0 360427R3QF
Coding: 303030393135313035444C56413033363034323752335146
Shop #: WSC 29869 002 104857

No fault code found.

Address 62: Door, Rear Left Labels: 4E0-910-802.lbl
Part No SW: 4E0 910 802 A HW: 4E0 959 801 D
Component: Türsteuer.HL BRM005 0180
Coding: 0032364
Shop #: WSC 02313 785 00200
VCID: 1E33B085C9B048B1C7-804A

2 Faults Found:

01308 - Control Module for Roof Electronics (J528)
004 - No Signal/Communication - Intermittent
Freeze Frame:
Fault Status: 00100100
Fault Priority: 4
Fault Frequency: 4
Reset counter: 154
Mileage: 163840 km
Time Indication: 0
Date: 2016.11.30
Time: 13:49:28

01299 - Diagnostic Interface for Data Bus (J533)
004 - No Signal/Communication - Intermittent
Freeze Frame:
Fault Status: 00100100
Fault Priority: 4
Fault Frequency: 2
Reset counter: 255
Mileage: 163840 km
Time Indication: 0
Date: 2016.11.30
Time: 13:49:28

VIN: WAUMV44E17N015584 License Plate:

Address 65: Tire Pressure Labels: 4E0-910-273.lbl
Part No SW: 4E0 910 273 A HW: 4F0 907 273 A
Component: Reifendruck 3 H05
Revision: 00050340 Serial number: 00000700049214
Coding: 0232125
Shop #: WSC 02313 785 00200
VCID: 204F8E7DF3C47E41F5-8074

1 Fault Found:

00532 - Supply Voltage B+
002 - Lower Limit Exceeded - Intermittent - MIL ON
Freeze Frame:
Fault Status: 10100010
Fault Priority: 3
Fault Frequency: 2
Reset counter: 154
Mileage: 166636 km
Time Indication: 0
Date: 2017.01.03
Time: 00:01:02

Freeze Frame:
(no units): 255.0
Voltage: 2.30 V
(no units): 42.0
Temperature: 0.0°C
Temperature: 0.0°C
Temperature: 0.0°C
Temperature: 0.0°C

Address 67: Voice Control Labels: 4E0-910-75x-67.lbl
Part No SW: 4E0 910 754 Q HW: 4E0 035 753 A
Component: SDS 3501 US H45 0630
Revision: 00000000 Serial number: 00000701230054
Shop #: WSC 12336 024 394758
VCID: 3467722D573CF2E101-8060

No fault code found.

VIN: WAUMV44E17N015584 License Plate:

Address 6C: Back-up Cam. Labels: 4E0-910-441.clb
Part No SW: 4E0 910 441 HW: 4L0 907 441 A
Component: J772 Rearview 0050
Revision: --H12--- Serial number: 525PA8-J6Z104D
Coding: 1120503
Shop #: WSC 02313 785 00200
VCID: 5CB7FA8D9F2C1AA1E9-8008

1 Fault Found:

00778 - Steering Angle Sensor (G85)
013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101
Fault Priority: 3
Fault Frequency: 1
Reset counter: 130
Mileage: 167626 km
Time Indication: 0
Date: 2017.01.18
Time: 17:50:20

Freeze Frame:

Term 15 On
Reverse OFF
Count: 3

Address 72: Door, Rear Right Labels: 4E0-910-802.lbl
Part No SW: 4E0 910 802 A HW: 4E0 959 802 D
Component: Türsteuer.HR BRM005 0180
Coding: 0032364
Shop #: WSC 02313 785 00200
VCID: 1E33B085C9B048B1C7-804A

1 Fault Found:

01308 - Control Module for Roof Electronics (J528)
004 - No Signal/Communication - Intermittent

Freeze Frame:

Fault Status: 00100100
Fault Priority: 4
Fault Frequency: 0
Reset counter: 154
Mileage: 166784 km
Time Indication: 0
Date: 2017.01.10
Time: 00:03:46

VIN: WAUMV44E17N015584 License Plate:

Address 76: Park Assist Labels: 4E0-910-283.lbl
Part No SW: 4E0 910 283 C HW: 4E0 919 283 C
Component: Parkhilfe 8-Kan H12 0040
Revision: 00H12000 Serial number: 08720701801170
Coding: 0221208
Shop #: WSC 02313 785 00200
VCID: 23458171E2D26559E8-8076

No fault code found.

Address 77: Telephone Labels: 4E0-910-336.lbl
Part No SW: 4F0 910 336 H HW: 4E0 862 335
Component: Handyvorb2 H16 1130
Revision: 00000000 Serial number: 00000007563175
Coding: 0010900
Shop #: WSC 00000 000 00000
VCID: 285F965D9BF48601BD-807C

No fault code found.

End----- (Elapsed Time: 03:40)-----