

## Quote

<b>RO Number</b>	219764
<b>Tag</b>	T5660

AUDI CENTRAL HOUSTON  
2120 SOUTHWEST FREEWAY  
HOUSTON TX 77098  
Phone # (713)596-3583

Customer Information			Vehicle Information			
<b>Customer #</b>	<b>Customer Name</b>	<b>Quote Date/Time</b>	<b>Year</b>	<b>Make</b>	<b>Model</b>	<b>Odometer</b>
200071	Anibal Pacheco	10/08/2018 03:06 PM	2009	AUDI	A8 L W12	79103
<b>Address</b>			<b>VIN</b>			
1107 W 4TH ST		FREEPORT, TX 77541-5301	WAUMR94EX9N005415			
<b>Phone #</b>	<b>Email Address</b>		<b>Advisor</b>		<b>Appt Promised: Date/Time</b>	
(979)900-4979			Flor I Fuentes		Yes 10/08/2018 07:00 PM	

### SERVICE REQUEST

Technician Number: 1641 Status: APPROVED

D SELF LEVELING SUSPENSION AIR COMPRESSOR IS NOT PRODUCING ENOUGH PRESSURE. NEED TO REPLACE PUMP, RELAY, AND AIR SOLENOID VALVE BLOCK TO START. NEED TO PRODUCE ENOUGH PRESSURE IN ORDER INSPECT AND VERIFY STRUT AIRBAGS ARE NOT LEAKING.

Additional Recommendation	Qty	LT	Hrs	Unit Price	Price
<b>Labor</b>					
SELF LEVELING SUSPENSION AIR COMPRESSOR IS NOT PRODUCING ENOUGH PRESSURE. NEED TO REPLACE PUMP, RELAY, AND AIR SOLENOID VALVE BLOCK TO START. NEED TO PRODUCE ENOUGH PRESSURE IN ORDER INSPECT AND VERIFY STRUT AIRBAGS ARE NOT LEAKING.	CC				
<b>Parts</b>					
4E0-616-007-E COMPRESSOR	1	CC			
4H0-951-253-A RELAY	1	CC			
4F0-616-013 VALVE	1	CC			

Pricing Summary					
	Labor	Parts	M/L/S	Tax	Line Total
Estimate	1,295.88	2,238.74	79.95	191.30	3,805.87

Additional Recommendations	
<b>Labor</b>	\$1,295.88
<b>Parts</b>	\$2,238.74
<b>Misc.</b>	\$79.95
<b>Lube</b>	\$0.00
<b>Sublet</b>	\$0.00
<b>Subtotal</b>	\$3,614.57
<b>Tax</b>	\$191.30
<b>Total</b>	\$3,805.87