

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64
VCDS Version: Release 23.11.0(x64) Data version: 20240322 DS351.0
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324

VIN: WAURV78T99A023572 License Plate:
Mileage: 263690km-163849mi Repair Order:

Chassis Type: 8T-AU48 (8T0)

Scan: 01 02 03 05 06 07 08 09 0E 0F 10 15 16 17 19 1E 36 37 3C 42
46 47 52 53 55 56 65 67 6C 77

VIN: WAURV78T99A023572 Mileage: 263690km-163849miles

01-Engine -- Status: Malfunction 0010
02-Auto Trans -- Status: OK 0000
03-ABS Brakes -- Status: OK 0000
04-Steering Angle -- Status: OK 0000
05-Acc/Start Auth. -- Status: OK 0000
06-Seat Mem. Pass -- Status: OK 0000
07-Control Head -- Status: OK 0000
08-Auto HVAC -- Status: Malfunction 0010
09-Cent. Elect. -- Status: Malfunction 0010
0E-Media Player 1 -- Status: OK 0000
0F-Digital Radio -- Status: Malfunction 0010
10-Park/Steer Assist -- Status: OK 0000
15-Airbags -- Status: Malfunction 0010
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
19-CAN Gateway -- Status: OK 0000
1E-Media Player 2 -- Status: OK 0000
36-Seat Mem. Dvr -- Status: OK 0000
37-Navigation -- Status: OK 0000
3C-Lane Change -- Status: Malfunction 0010
42-Door Elect, Driver -- Status: OK 0000
46-Central Conv. -- Status: Malfunction 0010
47-Sound System -- Status: OK 0000
52-Door Elect, Pass. -- Status: OK 0000
53-Parking Brake -- Status: Malfunction 0010
55-Headlight Range -- Status: OK 0000
56-Radio -- Status: OK 0000
65-Tire Pressure -- Status: OK 0000
67-Voice Control -- Status: OK 0000
6C-Back-up Cam. -- Status: OK 0000
77-Telephone -- Status: OK 0000

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324
Page 2

VIN: WAURV78T99A023572 License Plate:

Address 01: Engine (J623-CAUB) Labels: 079-907-560-CAU.clb
Part No SW: 8T0 907 560 N HW: 8T0 907 560
Component: 4.2l V8/4V H10 0003
Revision: 76H10---
Coding: 01140009190F0120
Shop #: WSC 38992 001 1048576
VCID: 45819CA3CCDFA2B9B0-8010
VINID: 9D1962987224249440083147085E867262

2 Faults Found:

005715 - Please check DTC Memory of ABS Controller

P1653 - 001 - - Intermittent

Freeze Frame:

Fault Status: 00100001
Fault Priority: 2
Fault Frequency: 1
Reset counter: 255
Mileage: 263694 km
Time Indication: 0
Date: 2008.05.27
Time: 01:33:47

Freeze Frame:

RPM: 0 /min
Load: 0.0 %
Speed: 0.0 km/h
Temperature: 17.0°C
Temperature: 28.0°C
Absolute Pres.: 990.0 mbar
Voltage: 12.319 V

005715 - Please check DTC Memory of ABS Controller

P1653 - 008 - - Intermittent

Freeze Frame:

Fault Status: 00101000
Fault Priority: 2
Fault Frequency: 2
Reset counter: 255
Mileage: 263694 km
Time Indication: 0
Date: 2008.05.27
Time: 01:33:47

Freeze Frame:

RPM: 0 /min
Load: 0.0 %
Speed: 0.0 km/h
Temperature: 17.0°C
Temperature: 28.0°C
Absolute Pres.: 990.0 mbar
Voltage: 12.319 V

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324
Page 3

VIN: WAURV78T99A023572 License Plate:

Readiness: 0110 1101

Address 02: Auto Trans (J217) Labels:| 0B6-927-156.clb
Part No SW: 8K0 927 158 B HW: 0B6 927 156
Component: 0B6 42 FSIUSA H04 0041
Revision: --H04---
Coding: 001002
Shop #: WSC 00000 000 00000
ASAM Dataset: EV_TCMAL651 A01004
ROD: EV_TCMAL651.rod
VCID: 3561EC63943F323920-8060

No fault code found.

Address 03: ABS Brakes (J104) Labels:. 8K0-907-379-V1.clb
Part No SW: 8K0 907 379 AB HW: 8K0 907 379 AB
Component: ESP8 quattro H04 0060
Revision: ----- Serial number: -----
Coding: 120500
Shop #: WSC 06325 000 00000
VCID: 79F92053F0A7165984-802C

No fault code found.

Address 05: Acc/Start Auth. (J393) Labels:. 8K0-907-064-05.clb
Part No SW: 8K0 907 064 AG HW: 8K0 907 064 AG
Component: BCM2 1.1 H80 0143
Revision: 00002001
Coding: 0D0000
Shop #: WSC 06325 000 00000
VCID: 75E12C63DCBF7239E0-8020

Subsystem 1 - Part No SW: 8T0 959 754 S HW: 8T0 959 754 S
Component: FBSAUDIB8 IDG H37 0060
Serial number: 0508000046632011

Subsystem 2 - Part No SW: 8K0 905 852 D HW: 8K0 905 852 D
Component: ELVAUDIB8 H36 0041
Serial number: 0208000070263013

No fault code found.

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324
Page 4

VIN: WAURV78T99A023572 License Plate:

Address 06: Seat Mem. Pass (J521) Labels: 8T0-959-760.clb
Part No SW: 8T0 959 760 B HW: 8T0 959 760 B
Component: MEM-BFS H09 0043
Revision: AA000000 Serial number: 00001001154717
Coding: 00017025002C00000000
Shop #: WSC 06325 000 00000
VCID: 428B87BFDDDF1958195-8016

No fault code found.

Address 07: Control Head Labels: 8T0-035-7xx-07-H.clb
Part No SW: 8T0 035 729 M HW: 4E0 035 729 A
Component: Interfacebox H43 4610
Revision: 00000000 Serial number: 340IT087512882
Coding: 0025003
Shop #: WSC 06325 000 00000
VCID: 438582BB02EB9C899E-8016

Subsystem 1 - Part No: 8T0 919 609 D
Component: E0380 BedienteilH08 0100

Subsystem 2 - Serial number: 00000000158364

Subsystem 3 - Serial number: 0123.09.080000000100010771ÿ

Subsystem 4 - Serial number: 010771ÿ

No fault code found.

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324
Page 5

VIN: WAURV78T99A023572 License Plate:

Address 08: Auto HVAC (J255) Labels: 8Tx-820-043-3Z.clb
Part No SW: 8T1 820 043 AC HW: 8T1 820 043 AC
Component: KLIMA 3 ZONEN H06 0140
Revision: C1000000 Serial number: 0125.09.081233
Coding: 48022000
Shop #: WSC 06325 000 00000
VCID: 72EB177FADD16501C5-8026

1 Fault Found:

01206 - Signal for Duration of Ignition Off Time

008 - Implausible Signal

Freeze Frame:

Fault Status: 01101000

Fault Priority: 7

Fault Frequency: 1

Reset counter: 58

Mileage: 263694 km

Time Indication: 0

Date: 2008.05.27

Time: 01:52:25

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324
Page 6

VIN: WAURV78T99A023572 License Plate:

Address 09: Cent. Elect. (J519) Labels: 8K0-907-063.clb
Part No SW: 8K0 907 063 D HW: 8K0 907 063 D
Component: BCM1 1.0 H22 0253
Revision: 05022001 Serial number: 00000000235573
Coding: 26001091073CAF010000080300003D3D0F1C538800010161000000
Shop #: WSC 12345 123 61029
VCID: 306FDD77635D171173-8064

Subsystem 1 - Part No SW: 8T1 955 119 C HW: 8J1 955 119 Labels: 1KX-955-119.CLB
Component: WWS 250908 H13 0040
Serial number: SWF08090250138
Coding: 00FD11

Subsystem 2 - Part No SW: 8K0 955 559 HW: 8K0 955 559 Labels: 8K0-955-559.CLB
Component: RLS H04 0003
Serial number: 10275612
Coding: 02532C

Subsystem 3 - Part No SW: 8K0 941 531 J HW: 8K0 941 531 J
Component: E1 - LDS H07 0070
Serial number: 00000000001109080536

1 Fault Found:

02258 - Door Opener Transmitter
004 - No Signal/Communication
Freeze Frame:
Fault Status: 01100100
Fault Priority: 3
Fault Frequency: 1
Reset counter: 58
Mileage: 263694 km
Time Indication: 0
Date: 2008.05.27
Time: 01:52:00

Address 0E: Media Player 1 Labels: 4E0-910-111.lbl
Part No SW: 8T1 035 110 C HW: 8T1 035 110 C
Component: MP3-Changer H43 0390
Revision: 00043003 Serial number: AUZ5ZBH8560408
Shop #: WSC 00000 000 00000
VCID: 2A5BCF1F85816DC1BD-807E

No fault code found.

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324
Page 7

VIN: WAURV78T99A023572 License Plate:

Address 0F: Digital Radio Labels: 4E0-910-593-SIR.lbl
Part No SW: 4E0 910 593 M HW: 4E0 035 593 F
Component: SDAR SIRIUS H07 0160
Revision: 00000000 Serial number: AUZ4Z7H0411429
Coding: 0000100
Shop #: WSC 06325 000 00000
VCID: 3169D873A8571E197C-8064

3 Faults Found:

00003 - Control Module

014 - Defective

Freeze Frame:

Fault Status: 01101110

Fault Priority: 5

Fault Frequency: 106

Reset counter: 189

Mileage: 152352 km

Time Indication: 0

Date: 2018.01.17

Time: 08:18:15

02635 - Tuner Not Enabled/Activated

000 - -

Freeze Frame:

Fault Status: 01100000

Fault Priority: 7

Fault Frequency: 1

Reset counter: 58

Mileage: 263694 km

Time Indication: 0

Date: 2008.05.27

Time: 01:52:36

02788 - Internal Communications Error

000 - -

Freeze Frame:

Fault Status: 01100000

Fault Priority: 7

Fault Frequency: 1

Reset counter: 58

Mileage: 263694 km

Time Indication: 0

Date: 2008.05.27

Time: 01:52:25

Freeze Frame:

Bin. Bits: 00000000

Bin. Bits: 00000001

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324
Page 8

VIN: WAURV78T99A023572 License Plate:

Address 10: Park/Steer Assist (J446) Labels: 8K0-919-475.clb
Part No SW: 8K0 919 475 D HW: 8K0 919 475
Component: PARKHILFE 4K H06 0020
Revision: 11001001 Serial number: 52930827300482
Coding: 200102
Shop #: WSC 06325 000 00000
VCID: 3A7BFF5FB521DD41CD-806E

No fault code found.

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:53:32324
Page 9

VIN: WAURV78T99A023572 License Plate:

Address 15: Airbags (J234) Labels:| 8K0-959-655.clb
Part No SW: 8K0 959 655 F HW: 8K0 959 655 F
Component: AirbagVW-AU10 H27 0410
Serial number: 0039KD14917O Dataset Number: 8T0909602J 0001
Coding: 3033333343303030304A55304C38543053
Shop #: WSC 06325 000 00000
ASAM Dataset: EV_AirbaECUVWAUDI010 A02007
ROD: EV_AirbaECUVWAUDI010_A02.rod
VCID: 408F8DB7DBFD879183-8014

Seat occupied recognition:
Subsystem 1 - Part No SW: 8K0 959 339 HW: 8K0 959 339
Component: BF-Gewichtss. H01 0050
Serial number: 5810000R080000163T

Crash sensor for side airbag: driver side:
Serial number: 6334MSME4065183FF

Front Passenger's Side Airbag Crash Sensor:
Serial number: 6344MSME413049331

Rear Side Airbag Crash Sensor (on driver's side):
Serial number: 6352QSME2C0D431EQ

Passenger side rear thorax airbag crash sensor:
Serial number: 6362QSME30070414/

Crash sensor for front airbag: driver side:
Serial number: 63732SME120A0010D

Crash sensor for front airbag: front passenger side:
Serial number: 63832SME110C1E06Z

1 Fault Found:

9444629 - Safety belt switch - passenger side
B101D 15 [10001001] - Open or Short to Plus
MIL ON - Confirmed - Tested Since Memory Clear
Freeze Frame:
Fault Priority: 2
Fault Frequency: 1
Mileage: 263694 km
Date: 2008.05.27
Time: 01:52:28

VIN: WAURV78T99A023572 License Plate:

Address 16: Steering wheel (J527) Labels: 8K0-953-568.clb
Part No SW: 8K0 953 568 F HW: 8K0 953 568 F
Component: Lenks.Modul H13 0013
Revision: ----- Serial number: 90315HIS00050
Coding: 000036
Shop #: WSC 06325 000 00000
VCID: 3D71F443A40FEA79E8-8068

Component: E221 - MFL H02 0003

No fault code found.

Address 17: Instruments (J285) Labels: 8T0-920-xxx-17.clb
Part No SW: 8T0 920 981 E HW: 8T0 920 981 E
Component: KOMBIINSTR. H31 0224
Revision: 00100000 Serial number: 9D96AX2A8
Coding: 831501000B00D705020000
Shop #: WSC 12345 123 61029
VCID: 3E73F34FA909F161F1-806A

No fault code found.

Address 19: CAN Gateway (J533) Labels: 8T0-907-468.clb
Part No SW: 8T0 907 468 L HW: 8T0 907 468 L
Component: GW-BEM 5CAN-M H10 0094
Revision: 4FB50047 Serial number: 4700F0890782E9
Coding: 000303
Shop #: WSC 06325 000 00000
VCID: 4A9BAF9FE5C14DC15D-801E

Subsystem 1 - Part No SW: 8K0 915 181 B HW: 8K0 915 181 B
Component: J367-BDM H04 0150
Serial number: 18046C97160908

No fault code found.

Address 1E: Media Player 2 (R199) Labels: 4E0-035-785.lbl
Part No SW: 4E0 035 785 F HW: 4E0 035 785 C
Component: SG ext.Player H15 0850
Revision: 00000000
Coding: 020000
Shop #: WSC 06325 000 00000
VCID: 2B55CA1B4A7B74C946-807E

No fault code found.

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:54:32324
Page 11

VIN: WAURV78T99A023572 License Plate:

Address 36: Seat Mem. Drvr (J136) Labels: 8T0-959-760.clb
Part No SW: 8T0 959 760 B HW: 8T0 959 760 B
Component: MEM-FS H09 0043
Revision: AA000000 Serial number: 00001001154443
Coding: 00197B25002C00000000
Shop #: WSC 06325 000 00000
VCID: 428B87BFDDF1958195-8016

No fault code found.

Address 37: Navigation Labels: 4E0-910-88x-37.lbl
Part No SW: 4E0 910 888 M HW: 4E0 919 887 M
Component: MNS US H52 1100
Revision: 00000000 Serial number: 341JZ087515838
Shop #: WSC 08307 444 59302
VCID: 387FE5574B2DCF513B-806C

No fault code found.

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:54:32324
Page 12

VIN: WAURV78T99A023572 License Plate:

Address 3C: Lane Change Labels: None
Part No SW: 8K0 907 566 B HW: 4L0 907 566 B
Component: J0769_SWA_MasterH01 0050
Revision: 00H01000 Serial number: 6PZ 009 014-13
Coding: 0000004
Shop #: WSC 06325 000 00000
VCID: 3663EB6F4139392129-8062

Subsystem 1 - Part No: 8K0 907 568 B
Component: J0770_SWA_Slave_H01 0050

Subsystem 2 - Serial number: 6PZ 009 014-33

Subsystem 3 - Serial number: 5F06.10.0800H010003CD10616ÿ

Subsystem 4 - Serial number: D10616ÿ

2 Faults Found:

02850 - Control Module 2 for Lane Change Assistance (J770)

014 - Defective

Freeze Frame:

Fault Status: 01101110

Fault Priority: 3

Fault Frequency: 1

Reset counter: 58

Mileage: 263694 km

Time Indication: 0

Date: 2008.05.27

Time: 01:52:25

02852 - Indicator Lamp for Lane Change Assistance (K232)

010 - Open or Short to Plus

Freeze Frame:

Fault Status: 01101010

Fault Priority: 3

Fault Frequency: 1

Reset counter: 58

Mileage: 263694 km

Time Indication: 0

Date: 2008.05.27

Time: 01:56:03

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:54:32324
Page 13

VIN: WAURV78T99A023572 License Plate:

Address 42: Door Elect, Driver (J386) Labels: 8K0-959-793.clb
Part No SW: 8T0 959 793 J HW: 8T0 959 793 D
Component: TSG FA H07 1301
Revision: ----- Serial number: -----
Coding: 011C13224E00120102
Shop #: WSC 12345 123 61029
VCID: 50AFBDF7039D771113-8004

No fault code found.

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:54:32324
Page 14

VIN: WAURV78T99A023572 License Plate:

Address 46: Central Conv. (J393) Labels: 8K0-907-064-46.clb
Part No SW: 8K0 907 064 AG HW: 8K0 907 064 AG
Component: BCM2 1.1 H80 0143
Revision: 00002001 Serial number: 0114775926
Coding: 0106029A007A448500B000
Shop #: WSC 12345 123 61029
VCID: 75E12C63DCBF7239E0-8020

Subsystem 1 - Part No SW: 8K0 959 719 HW: 8K0 959 719
Component: GTO BF H06 0040
Serial number: 00000000000000077028

Subsystem 2 - Part No: 1K0 951 605 C
Component: LIN BACKUP HO H03 1301

Subsystem 3 - Part No SW: 8R0 959 591 A HW: 8R0 959 591
Component: J245EE19SKB12 H01 0220
Serial number: 0123456789ABCDEFGHIJ

2 Faults Found:

00218 - Humidity Sensor (G355)

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 2

Fault Frequency: 1

Reset counter: 58

Mileage: 263694 km

Time Indication: 0

Date: 2008.05.27

Time: 01:52:29

02772 - Bulb for Right Brake / Turn Signal / Tail Lamp (M70)

012 - Electrical Fault in Circuit - MIL ON

Freeze Frame:

Fault Status: 11101100

Fault Priority: 2

Fault Frequency: 1

Reset counter: 58

Mileage: 263694 km

Time Indication: 0

Date: 2008.05.27

Time: 01:52:52

VIN: WAURV78T99A023572 License Plate:

Address 47: Sound System (J525) Labels: 8T0-035-223-BOM.clb
Part No SW: 8T0 035 223 T HW: 8T0 035 223 F
Component: DSP Prem H14 0400
Revision: 00H14003 Serial number: 34814003178601
Coding: 030101
Shop #: WSC 12336 024 394758
VCID: 3F8D8E4BAE03F869FA-806A

No fault code found.

Address 52: Door Elect, Pass. (J387) Labels: 8K0-959-792.clb
Part No SW: 8T0 959 792 J HW: 8T0 959 792 D
Component: TSG BF H07 1301
Revision: ----- Serial number: -----
Coding: 011C13224E00120102
Shop #: WSC 12345 123 61029
VCID: 4FADBE8B1EA368E90A-801A

No fault code found.

Address 53: Parking Brake (J540) Labels: 8K0-907-801-V1.clb
Part No SW: 8K0 907 801 E HW: 8K0 907 801 E
Component: EPB Audi B8 H05 0060
Revision: 00000003 Serial number: 00000000232217
Shop #: WSC 00000 000 00000
VCID: 3169D87368571E197C-8064

1 Fault Found:

01321 - Control Module for Airbags (J234)

013 - Check DTC Memory - MIL ON

Freeze Frame:

Fault Status: 11101101

Fault Priority: 4

Fault Frequency: 2

Reset counter: 58

Mileage: 263694 km

Time Indication: 0

Date: 2008.05.27

Time: 01:52:25

Freeze Frame:

Voltage: 12.00 V

Count: 80

Speed: 0.0 km/h

Hex Value: 0x0270

Hex Value: 0x0001

Hex Value: 0x0101

VIN: WAURV78T99A023572 License Plate:

Address 55: Headlight Range Labels: 8T0-907-357.clb
Part No SW: 8H0 907 357 A HW: 8H0 907 357
Component: AFS 1 H01 0020
Revision: 00000001 Serial number:
Coding: 0000017
Shop #: WSC 06324 000 00000
VCID: 306FDD77A35D171173-8064

Subsystem 1 - Part No: 7L6 941 329 A
Component: AFS-Modul links H07 0004

Subsystem 2 - Part No: 7L6 941 329 A
Component: AFS-Modul rechtsH07 0004

No fault code found.

Address 56: Radio Labels: 4E0-910-541.lbl
Part No SW: 4E0 910 541 T HW: 4F0 035 541 N
Component: TUNER EU/US/RDW H42 0630
Revision: 00000000 Serial number: 3571 087509535
Coding: 0000002
Shop #: WSC 06325 000 00000
VCID: 3169D873A8571E197C-8064

No fault code found.

Address 65: Tire Pressure (J502) Labels: 8K0-907-273.clb
Part No SW: 8K0 907 273 A HW: 8K0 907 273 A
Component: J502-RDK H03 0250
Revision: 00001001 Serial number: 13140781806106
Coding: 0CD154
Shop #: WSC 06324 000 00000
VCID: 306FDD77635D171173-8064

No fault code found.

Address 67: Voice Control Labels: 4E0-910-75x-67.lbl
Part No SW: 4E0 910 754 Q HW: 4E0 035 753 A
Component: SDS 3501 US H46 0630
Revision: 00000000 Serial number: 00000809110448
Shop #: WSC 12336 024 394758
VCID: 3467D16757452B3117-8060

No fault code found.

VCDS
Self-Diagnosis Log
Friday,26,April,2024,21:21:54:32324
Page 17

VIN: WAURV78T99A023572 License Plate:

Address 6C: Back-up Cam. Labels: 8T0-907-441.clb
Part No SW: 8T0 907 441 B HW: 4L0 907 441 A
Component: J772_Rearview 0070
Revision: --H12--- Serial number: 525PA8-J899083
Coding: 1000008
Shop #: WSC 06325 000 00000
VCID: 377DE66B4633C02932-8062

No fault code found.

Address 77: Telephone Labels: 4E0-910-336.lbl
Part No SW: 4F0 910 336 H HW: 4E0 862 335
Component: Handyvorb2 H20 1130
Revision: 00000000 Serial number: 00000005062513
Coding: 0010900
Shop #: WSC 06325 000 00000
VCID: 285F35179B8D5FD1AB-807C

No fault code found.

End------(Elapsed Time: 04:10)-----