

Account

Vehicle

Help

Search

Contact

AutoZone Community

Exit

Your Vehicle: 2010 Audi Q7 Quattro (4LB) V6-3.0L DSL Turbo (CATA)



SAVE \$25

instantly on 4 tires!

tirebuyer.com

SAVE NOW >

SAVE \$25

instantly on 4 tires!

tirebuyer.com

SAVE NOW >

[Vehicle](#) » [Heating and Air Conditioning](#) » [Service and Repair](#) » [Removal and Replacement](#) » [Rear HVAC Components](#) » [Right Rear Temperature Door Motor \(V314\)](#)


Right Rear Temperature Door Motor (V314)

Right Rear Temperature Door Motor (V314)

⌘ With the Right Rear Temperature Door Position Sensor (G392)

Removing

- Switch off ignition.
- Remove left side wall trim in luggage compartment..
- Remove (unhook) lever - 2 - from Right Rear Temperature Door Motor.



- Remove screws - **1** -.
- Disconnect electrical connection from Right Rear Temperature Door Motor and remove control motor.

Installing

- Install the removed components again in reverse order.
- Check DTC memory of Climatronic Control Module (J255) (and of Rear A/C Display Control Head (E265)) and erase any DTCs displayed using Vehicle Diagnosis, Testing and Information System VAS5051 in the "Guided Fault Finding" function.
- If necessary, perform a basic setting and output diagnostic test mode on the A/C system using Vehicle Diagnosis, Testing and Information System VAS5051 in the "Guided Fault Finding" function.

[Account](#) | [Vehicle](#) | [Help](#) | [Contact](#) | [AutoZone Community](#) | [Exit](#)