

Log-WAUZZZ8R3EA032427

Saturday, 03, February, 2018, 17:11:22:03057

VCDS -- Windows Based VAG/VAS Emulator Running on Windows 10 x64 (Parallels)

VCDS Version 18.1.0.2 (x64) HEX-NET CB: 0.4411.4

Data version: 20180122 DS285.1

www.Ross-Tech.com

VIN: WAUZZZ8R3EA032427 License Plate:

Address C0: Act. for Ext. Noise Labels: 4G0-907-160.CLB

Control Module Part Number: 8R0 907 160 HW: 4G0 907 160 B

Component and/or Version: SAS-GEN 2 AGA H09 0002

Software Coding:

Work Shop Code:

ASAM Dataset: EV_ActuaForExterNoiseUDS 003013 (AU48)

ROD: EV_ActuaForExterNoiseUDS.rod

VCID: 71AA337DA0A2EBCD4A-8025

4 Faults Found:

0005 - Incorrect Vehicle Type

U10D9 00 [008] - -

[Keine Funktion durch Falschverbau im Fahrzeug--> keine Funktion]

Intermittent - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 7

Fault Frequency: 1

Reset counter: 194

Mileage: 159953 km

Date: 2018.01.25

Time: 18:09:23

0006 - Actuator 1 for Engine Noise Simulation

C113C 13 [008] - Open Circuit

Intermittent - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 4

Fault Frequency: 254

Reset counter: 212

Mileage: 145644 km

Date: 2017.09.15

Time: 13:19:11

0010 - Databus

U1121 00 [008] - Missing Message

[Keine Funktion durch CAN Fehler Motorsteuergerätebotschaft fehlt-->
keine Klangerzeugung]

Intermittent - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Log-WAUZZZ8R3EA032427

Fault Priority: 6
Fault Frequency: 2
Reset counter: 211
Mileage: 162162 km
Date: 2018.02.03
Time: 14:23:36

0014 - Databus

U1121 00 [008] - Missing Message

[Keine Funktion durch CAN FehlerESPsteuergerätebotschaft fehlt-->

keine Klangerzeugung]

Intermittent - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001
Fault Priority: 6
Fault Frequency: 2
Reset counter: 211
Mileage: 162162 km
Date: 2018.02.03
Time: 14:23:36

Address C0: DTCs cleared