
IGNITION SWITCH

HEADLIGHT SWITCH




1996 - 2001 B5 AUDI A4 HEADLIGHT POWER SWITCH ADDED RELAYS MODIFICATION.

PREVENTS INTERNAL FAILURE
OF HEADLIGHT SWITCH DUE TO
OVERHEAT AND MELTING OF THE
POWER CONTACT CARRIER
CAUSING INOPERATIVE
HEADLIGHTS.

ALL WIRING MODIFICATION
SPLICES LOCATED AT HEADLIGHT
SWITCH CONNECTOR.

RELAYS REMOTE MOUNTED AT RELAY PANEL.

FAILED HEADLIGHT SWITCH WILL REQUIRE REBUILD REPAIR.



HEADLIGHT ASSEMBLIES

PRODUCED BY AN AUTODESK EDUCATIONAL PRODUC

DRAWING CREATED BY: ADAM P B BIERLEIN