

VIN: WAUUL78E96A184873 License Plate:

Address 55: Headlight Range Labels: 4F0-910-357.lbl
Part No SW: 4F0 910 357 E HW: 4F0 907 357 E
Component: AFS 1 H01 0010
Revision: 00000001 Serial number:
Coding: 0000019
Shop #: WSC 06435 000 00000
VCID: 285FA45C9B63B1044C-807C

Subsystem 1 - Part No: 8E0 941 329
Component: AFS-Modul links H03 0020

Subsystem 2 - Part No: 8E0 941 329
Component: AFS-Modul rechtsH03 0020

2 Faults Found:

02234 - Right Headlight Power Output Stage (J668)
014 - Defective - MIL ON

Freeze Frame:

Fault Status: 11101110
Fault Priority: 2
Fault Frequency: 1
Reset counter: 40
Time Indication: 0

02233 - Left Headlight Power Output Stage (J667)
004 - No Signal/Communication - Intermittent

Freeze Frame:

Fault Status: 00100100
Fault Priority: 2
Fault Frequency: 1
Reset counter: 39
Time Indication: 0
