

Vehicle diagnostic report



Shop Name:
 Address:
 Telephone:
 Email :
 Fax:

Owner name: rev it
 License #: adesa S6
 Make: Audi
 Model:
 Year: 2014
 VIN: WAUF2AFC9EN003093
 ODO: 136213 (km)
 Vehicle Software Version: V28.21
 Diagnostic Application Version: V5.00.026
 Test Time: 2018-12-29 14:33:00
 Tester: dan
 Diagnostic path: Health Report



Diagnostic Result

Fault	(14)	
01 Engine Electronics	(1)	Abnormal
	U100800 Diagnostic interface for data bus - Read out DTC	active/static
13 Distance Control	(1)	Abnormal
	U111300 Function limitation due to received malfunction value	active/static
19 Gateway Data Bus	(1)	Abnormal
	U105200 Generator - No Communication	active/static
22 4WD Electronics	(1)	Abnormal
	U111300 Function limitation due to received malfunction value	passive/abiogenesis
34 Self Leveling Suspension	(1)	Abnormal
	C104807 Level control system sensor - mechanical malfunction	active/static
42 Driver-Door Elect.	(2)	Abnormal
	02123 Door warning light / entry light	Electrical Fault in Circuit
	03297 Driver lock cylinder contact switch	Implausible Signal
46 Central Control Module	(4)	Abnormal

	02772 Right brake lamp/turn signal/tail lamp bulb	Electrical Fault in Circuit
	01699 Rear lid ctr. lock. sys. motor	Open or Short to Ground
	02743 Right brake lamp/turn signal bulb	Electrical Fault in Circuit
	01519 Right back-up light bulb	Electrical Fault in Circuit
47 Soundsystem	(1)	Abnormal
	00870 Left front bass speaker	Open Circuit
53 Parking Brake	(1)	Abnormal
	U111300 Function limitation due to received malfunction value	passive/abiogenesis
55 Headlight Range Control	(1)	Abnormal
	U111300 Function limitation due to received malfunction value	passive/abiogenesis
85 On Board Cam.	(1)	Abnormal
	U111300 Function limitation due to received malfunction value	passive/abiogenesis
8B Adaptive Cruise 2	(1)	Abnormal
	U111300 Function limitation due to received malfunction value	passive/abiogenesis
8E Image Processing	(3)	Abnormal
	U111300 Function limitation due to received malfunction value	passive/abiogenesis
	U111300 Function limitation due to received malfunction value	passive/abiogenesis
	C110800 Function limitation due to missing image information	passive/abiogenesis
BA Motor Mounts	(3)	Abnormal
	B201000 No basic setting	active/static
	B200500 Data record invalid	active/static
	C113107 Actuator 1 for assembly mounting - mechanical malfunction	active/static

Normal (23)

02 Transmission Electronics	Normal
03 Brake Electronics	Normal
05 Access & Permissi.	Normal
08 AC/Heating Electronics	Normal
09 Electronic Ctrl Electronics	Normal
10 Parking Assist System 2	Normal
15 Airbags	Normal

16 Steering Wheel Electronics	Normal
17 Instrument Cluster	Normal
28 Climate Control Unit Rear	Normal
36 Driver`s Side Seat Adj.	Normal
3B Sensor Elect.	Normal
3C Lane Departure Assistance System	Normal
44 Steering Assistance	Normal
52 Passe.-Door Elect.	Normal
56 Radio	Normal
5F Information Electronic equipment 1	Normal
62 LR-Door Electroni.	Normal
6C Rear Camera	Normal
72 RR-Door Electroni.	Normal
8F Pretens. Frt Left	Normal
90 Pretens. Frt Right	Normal
A9 Struct.Borne Sound	Normal